

County Surveyor's Record, Douglas County, Oregon

Subdivision of Sec. 5, T. 24 S., R. 7 W.

CHAINS	
	<p>in the ground, with brass cap mkd.</p> <p style="text-align: center;">C $\frac{1}{4}$ S 5 1963</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 23 ins. diam., bears N. $60\frac{1}{2}^{\circ}$ E., 68 lks. dist., mkd. C $\frac{1}{4}$ S5 BT.</p> <p style="padding-left: 40px;">A fir, 27 ins. diam., bears S. $57\frac{1}{4}^{\circ}$ W., 30 lks. dist., mkd. C $\frac{1}{4}$ S5 BT.</p> <p>Descend 200 ft. over NW. slope.</p>
57.70	Dirt road, 20 lks. wide, bears E. and SW., leave timber, enter open meadow, edge bears same as road.
58.00	Board fence, bears NE. and SW.
60.31	Point for the center N 1/16 sec. cor. of sec. 5.
	<p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 21 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">C N 1/16 S 5 C 1963</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears N. $81\frac{1}{2}^{\circ}$ E., 61 lks. dist., mkd. CN 1/16 S5 BT.</p> <p style="padding-left: 40px;">A cedar, 25 ins. diam., bears N. 40° W., 53 lks. dist., mkd. CN 1/16 S5 BT.</p> <p>Descend 10 ft. over N. slope.</p>
61.40	McGee Creek, 10 lks. wide, course E.; asc. 150 ft. over S. slope.
65.00	Enter timber, edge bears E. and W.
69.05	Dirt road, 20 lks. wide, bears NE. curving N., and SW.
70.25	Board fence, bears W. and SW.
70.40	Spur, slopes E.; desc. 40 ft. over N. slope.
71.60	Same road, bears N. 10° W. and S. 10° E.
76.77	The $\frac{1}{4}$ sec. cor. of sec. 5 only, on the N. bdy. of the Tp.
	<p>From the $\frac{1}{4}$ sec. cor. of secs. 4 and 5.</p> <p>N. $89^{\circ} 52'$ W., on the E. and W. center line of sec. 5.</p> <p>Ascend 35 ft. over NE. slope, through moderate timber and undergrowth.</p>
1.15	Fence, bears W. and SE., enter prairie, edge bears W. and SE.