

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, East Boundary, T. 24 S., R. 7 W.

CHAINS

A fir, 10 ins. diam., bears N. $7\frac{1}{2}^{\circ}$ E., 125 lks. dist., mkd. $\frac{1}{4}$ S36 BT.

A fir, 9 ins. diam., bears S. 71° W., 88 lks. dist., mkd. X BT. (No other suitable bearing tree available, N. of line)

The 1957 bearing trees have been destroyed.

Descend 85 ft. over SW. slope.

46.82 Creek, 2 lks. wide, course S. 30° W.; asc. 47 ft. over SE. slope.

56.36 Spur, slopes S.; desc. 285 ft. over SW. slope.

70.41 Road, unimproved, 20 lks. wide, bears N. 25° E. and S. 25° W.

77.20 Road, unimproved, 25 lks. wide, bears N. and S.

77.48 The cor. of secs. 35 and 36, only, on the S. bdy. of T. 23 S., R. 7 W., monumented with an iron post, 2 ins. diam., firmly set, protruding 12 ins. above the ground, with brass cap marked and witnessed as described in the official record.

Land, mountainous.

Soil, sandy loam, rock outcrops.

Timber, fir, hemlock, and cedar; undergrowth, salal, vine maple, madrone, alder, and arrowwood.

GENERAL DESCRIPTION

The general description of this area is as described in the official record of the 1957 dependent resurvey.