

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of S. Bdy., T. 21 S., R. 7 W.

CHAINS

## COUNTY SURVEYOR'S OFFICE

T 21 S		
S 32	S 33	R
S 5	S 4	7
T 22 S		W
1962		

from which the original bearing trees

A fir snag, 38 ins. diam., bears N. 50° E.,  
6 lks. dist., with a healed blaze. (Record  
bearing, N. 65° E.)

A cedar snag, 28 ins. diam., bears S. 30° E.,  
22 lks. dist., with no marks remaining.

A fir, 52 ins. diam., bears S. 45° W., 43 lks.  
dist., with fragmentary scribe marks visible  
on opened blaze.

A down fir, 20 ins. diam., the stump hole of  
which, bears N. 25° W., 43 lks. dist., with  
a healed blaze.

and trees marked by the County Surveyor

A fir, 30 ins. diam., bears N. 63½° E., 87 lks.  
dist., with a pitched over double blaze.

A hemlock, 5 ins. diam., bears S. 17¾° E.,  
22 lks. dist., with scribe marks T22S R7W S4 CS  
BT visible on unhealed double blaze.

A white fir, 6 ins. diam., bears S. 34° W., 22  
lks. dist., with scribe marks T22S R7W S5 CS BT  
visible on unhealed double blaze.

A hemlock, 10 ins. diam., bears N. 62¼° W., 17½  
lks. dist., with scribe marks T21S R7W S32 CS  
BT visible on unhealed double blaze.

N. 89° 51' W., bet. secs. 5 and 32, marking and blazing  
the true line.

Ascend 145 ft. over broken SE. slope through heavy  
timber and dense undergrowth.

10.65 Spur, slopes S.; desc. 80 ft. over broken SW. slope.

16.80 Creek, 1 lk. wide, course S. 40° E.; asc 380 ft. over  
general E. slope.

26.90 Ridge, bears N. 10° W. and S. 10° E.; desc. 94 ft. over  
SW. slope.

39.01 Point for the ¼ sec. cor. of secs. 5 and 32 at pro-  
portionate distance; there is no remaining evidence of  
the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins.  
in the ground, with brass cap marked

T 21 S		
¼	S 32	
	S 5	
T 22	S R 7 W	
	1964	