

## County Surveyor's Record, Douglas County, Oregon

## Dependent Resurvey, Subdivisional Lines, T. 21 S., R. 7 W.

CHAINS

A cedar, 25 ins. diam., bears S. 28° E., 93 lks. dist., mkd. T21S R7W S27 BT.

A cedar, 43 ins. diam., bears N. 28° W., 79 lks. dist., mkd. T21S R7W S21 BT.

Deposit the Haines' monument alongside the iron post.

N. 89° 47' W., bet. secs. 21 and 28.

Ascend 270 ft. over SE. slope, through heavy timber and dense undergrowth.

11.45 Spur, slopes N. 65° E.; asc. 48 ft. along N. slope.

12.35 Top of ascent, slopes N.; desc. 191 ft. over NW. slope.

24.45 Ravine, drains NE.; asc. 428 ft. over E. slope.

31.35 Ridge, bears N. 35° W. and S. 35° E.; desc. 143 ft. over W. slope.

38.35 Point for the  $\frac{1}{4}$  sec. cor. of secs. 21 and 28, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

$$\begin{array}{c} \frac{1}{4} \text{ S } 21 \\ \text{S } 28 \\ \text{T } 21 \text{ S } \text{ R } 7 \text{ W} \\ 1964 \end{array}$$

from which

A fir, 10 ins. diam., bears N. 33° E., 11 lks. dist., mkd.  $\frac{1}{4}$  S21 BT.

A fir, 11 ins. diam., bears S.  $13\frac{1}{4}$ ° E., 15 lks. dist., mkd.  $\frac{1}{4}$  S28 BT.

Descend 310 ft. over NW. slope.

45.90 Ravine, drains N. 15° W.; asc. 170 ft. over NE. slope.

51.50 Spur, slopes N. 20° E.; desc. 112 ft. over NW. slope.

56.05 Ravine, drains N. 35° E.; asc. 404 ft. over E. slope.

64.15 Spur, slopes N. 35° E.; desc. 288 ft. over NW. slope.

70.50 Ravine, drains N. 10° E.; asc. 358 ft. over general E. slope.

76.70 The cor. of secs. 20, 21, 28, and 29.

Land, mountainous.

Soil, sandy and rocky clay.

Timber, fir, hemlock, cedar, maple, alder, and chinquapin; undergrowth, vine maple, hazel, arrowwood, salmonberry, huckleberry, and fern.

N. 6° 02' W., bet. secs. 20 and 21.

Descend 283 ft. over N. slope, through heavy timber and dense undergrowth.