

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 21 S., R. 7 W.

CHAINS	
	<p>from which new bearing trees</p> <p>A hemlock, 5 ins. diam., bears N. $41\frac{1}{2}^{\circ}$ W., 35 lks. dist., mkd. $\frac{1}{4}$ S29 BT.</p> <p>A hemlock, 9 ins. diam., bears S. 28° W., 43 lks. dist., mkd. $\frac{1}{4}$ S32 BT.</p> <hr/> <p>N. $89^{\circ} 43'$ W., beginning new measurement.</p> <p>Ascend 786 ft. over broken E. slope changing to SE. slope.</p>
22.85	Spur ridge, bears N. 20° E. and S. 20° W.; desc. 48 ft. over W. slope.
29.70	Ravine, drains S. 15° W.; asc. 56 ft. over SE. slope.
32.70	Ridge, bears N. 30° E. and S. 30° W.; desc. 133 ft. over W. slope.
40.07	The cor. of secs. 29, 30, 31, and 32.
	<p>Land, mountainous. Soil, sandy and rocky clay. Timber, fir, hemlock, cedar, maple, alder, and chin- quapin; undergrowth, vine maple, salmonberry, hazel, huckleberry, arrowwood, salal, poison oak, Oregon grape, and fern.</p>
	<p>S. $87^{\circ} 49'$ W., bet. secs. 30 and 31.</p> <p>Descend 323 ft. over general W. slope, through heavy timber and dense undergrowth.</p>
13.25	Creek, 2 lks. wide, course N. 60° W.; asc. 109 ft. over broken NE. slope.
16.80	Spur, slopes N. 15° E.; desc. 32 ft. over NW. slope.
18.80	Point for the E $1/16$ sec. cor. of secs. 30 and 31.
	<p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked</p> <p style="text-align: center;"> $\begin{array}{r} \text{E } 1/16 \quad \text{S } 30 \\ \quad \quad \quad \text{S } 31 \\ \quad \quad \quad 1964 \end{array}$ </p>
	<p>from which</p> <p>A fir, 24 ins. diam., bears N. 20° W., $21\frac{1}{2}$ lks. dist., mkd. E $1/16$ S30 BT.</p> <p>A fir, 30 ins. diam., bears S. $13\frac{1}{2}^{\circ}$ W., 48 lks. dist., mkd. E $1/16$ S31 BT.</p> <p>Descend 10 ft. over NW. slope.</p>
19.20	Bottom of descent, slopes N.; asc. 192 ft. over NE. slope.
25.45	Ridge, bears N. 40° W. and S. 40° E.; desc. 57 ft. over SW. slope.