

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of E. Bdy., T. 23 S., R. 8 W.

CHAINS

The corner falls on top of ascent, slopes W.

Descend 230 ft. over NW. slope.

32.60 2 strand power line, bears N. 42° E. and S. 42° W.

33.30 Graveled road, 20 lks. wide, bears N. 45° E. and S. 45° W.

40.98 The cor. of secs. 13, 18, 19, and 24, perpetuated with an iron water pipe, 18 ins. long, 2½ ins. diam., firmly set 10 ins. in the ground, from which the remains of an original bearing tree:

A fir snag, 32 ins. diam., bears N. 45° E.,  
17 lks. dist., with no marks remaining.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked

T 23 S
R 8 W R 7 W
S 13   S 18
S 24   S 19
1964

from which new bearing trees

A fir, 10 ins. diam., bears N. 34½° E., 27 lks. dist., mkd. T23S R7W S18 BT.

A fir, 8 ins. diam., bears S. 69½° E., 71 lks. dist., mkd. T23S R7W S19 BT.

A fir, 15 ins. diam., bears S. 71¾° W., 98 lks. dist., mkd. T23S R8W S24 BT.

A fir, 25 ins. diam., bears N. 70° W., 96 lks. dist., mkd. T23S R8W S13 BT.

Deposit the water pipe alongside the iron post.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, maple, oak, and madrone; undergrowth, vine maple, arrowwood, hazel, salmon-berry, huckleberry, poison oak, Oregon grape, salal, and fern.

N. 0° 50' E., bet. secs. 13 and 18.

Descend 10 ft. over N. slope, through scattering timber and dense undergrowth.

2.20 Mehl Creek, 25 lks. wide, course E.; asc. 490 ft. over SE. slope, through dense brush, along the W. edge of logged area.

22.60 Spur ridge, bears E. and W.; desc. 420 ft. over NE. slope.

39.32 Point for the ¼ sec. cor. of secs. 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.