

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 23 S., R. 8 W.

CHAINS

T 23 S R 8 W
 S 26 | S 25
 S 35 | S 36
 1964

from which new bearing trees

A fir, 5 ins. diam., bears N. 74° E., 51 lks. dist., mkd. T23S R8W S25 BT.

A hemlock, 8 ins. diam., bears S. 75° E., 109 lks. dist., mkd. T23S R8W S36 BT.

A fir, 5 ins. diam., bears S. 46° W., 91 lks. dist., mkd. T23S R8W S35 BT.

A fir, 5 ins. diam., bears N. 84° W., 87 lks. dist., mkd. T23S R8W S26 BT.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, maple, oak, alder, madrone, and willow; undergrowth, vine maple, hazel, arrowwood, poison oak, ceanothus, salmonberry, blackberry, huckleberry, Oregon grape, salal, and fern.

N. 0° 01' E., bet. secs. 25 and 26.

Descend 200 ft. over NE. slope, through light brush, along the E. edge of logged area.

16.80 Creek, 1 lk. wide, course N. 50° E.; asc. 20 ft. over SE. slope.

20.03 Point for the S 1/16 sec. cor. of secs. 25 and 26.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap marked

S 1/16
 S 26 | S 25
 1964

from which

A hemlock, 10 ins. diam., bears S. 70½° E., 32 lks. dist., mkd. S 1/16 S25 BT.

A cedar, 15 ins. diam., bears N. 43° W., 53 lks. dist., mkd. S 1/16 S26 BT.

The corner falls at NE. cor. of logged area, edge bears S. and W. and at top of ascent, slopes E.

Descend 100 ft. over NE. slope, through heavy timber and dense undergrowth.

26.10 Creek, 4 lks. wide, course S. 50° E.; asc. 330 ft. over SE. slope.

32.59 An original line tree, a fir, 55 ins. diam., marked with 2 notches on the N. and S. faces.

40.06 Point for the ¼ sec. cor. of secs. 25 and 26, at proportionate distance as based on the original line tree to the S. and the original corner of secs. 23, 24, 25, and 26; there is no remaining evidence of the original corner.