

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 23 S., R. 8 W.

CHAINS

from which

A fir, 40 ins. diam., bears N. 12° E., 92 lks. dist., mkd. $\frac{1}{4}$ S24 BT.

A fir, 45 ins. diam., bears S. 2° W., 64 lks. dist., mkd. $\frac{1}{4}$ S25 BT.

Descend 240 ft. over W. slope.

56.20 Creek, 2 lks. wide, course N.; asc. 20 ft. over NE. slope.

59.30 Creek, 1 lk. wide, course N. 45° E.; asc. 60 ft. over NE. slope.

60.52 Point for the W 1/16 sec. cor. of secs. 24 and 25.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

W 1/16 $\frac{S}{S}$ $\frac{24}{25}$
1964

from which

A hemlock, 8 ins. diam., bears N. 58 $\frac{1}{2}$ ° W., 36 lks. dist., mkd. W 1/16 S24 BT.

A fir, 8 ins. diam., bears S. 81° W., 27 lks. dist., mkd. W 1/16 S25 BT.

Ascend 220 ft. over NE. slope.

66.50 Spur, slopes N.; desc. 20 ft. along N. slope.

80.33 The cor. of secs. 23, 24, 25, and 26.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, maple, madrone, oak, and dogwood; undergrowth, vine maple, hazel, arrowwood, salmonberry, huckleberry, poison oak, young timber, Oregon grape, salal, huckleberry, blackberry, and fern.

The following field notes describe the remonumentation of a certain original corner point, in T. 23 S., R. 8 W., as provided for in the General Special Instructions, Group No. 350, Oregon, dated May 3, 1957, "Investigation of Collateral or Physical Evidence of Corner Positions and Accessories Followed by Remonumentation of Corner Points, With New Accessories When Needed".

(Remonumentation of the corner established by
Williams R. Whipple, in 1894)

The $\frac{1}{4}$ sec. cor. of secs. 23 and 26, determined at record bearing and distance from the original bearing trees: