

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of S. Bdy., T. 28 S., R. 8 W.

CHAINS

A fir, 16 ins. diam., bears N. $49\frac{3}{4}^\circ$ E., 134 lks. dist., mkd. $\frac{1}{4}$ S31 BT.

A fir, 6 ins. diam., bears S. $49\frac{3}{4}^\circ$ W., 166 lks. dist., mkd. $\frac{1}{4}$ S6 BT.

From this point an iron pipe, $\frac{3}{4}$ in. diam., 3 ins. above ground, firmly set, bears S. $6^\circ 45'$ E., 0.10 chs. dist.

Ascend 25 ft. over gradual E. slope.

60.27

Point for the W 1/16 sec. cor. of secs. 6 and 31.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

W 1/16 $\frac{S 31}{S 6}$
1964

Fd. OK by County Surveyor's Office 5-13-76, C.S. #59/15-2

from which

An oak, 15 ins. diam., bears N. 32° W., $35\frac{1}{2}$ lks. dist., mkd. W 1/16 S31 BT.

A fir, 13 ins. diam., bears S. 20° W., 20 lks. dist., mkd. W 1/16 S6 BT.

From this point an iron pipe, 1 in. diam., 16 ins. above ground, firmly set, bears N. $84^\circ 30'$ E., 0.395 chs. dist.

Ascend 35 ft. over gradual E. slope.

61.10

NE. corner of cultivated field, continue along N. edge of field.

69.00

Top of ascent, slopes S. 30° E.; desc. 10 ft. over gentle SW. slope.

72.00

Bottom of descent, slopes S.; asc. 10 ft. over gentle SE. slope.

77.00

NW. corner of cultivated field; enter heavy young timber and dense undergrowth.

81.57

The cor. of Tps. 28 and 29 S., Rs. 8 and 9 W., monumented with an iron post, $2\frac{1}{2}$ ins. diam., 2 ins. above ground, firmly set, with brass cap mkd.

T 28 S
R 9 W R 8 W
S 36 | S 31
S 1 | S 6
T 29 S
1959

from which local bearing trees

A sawed cedar stump, 24 ins. diam., bears N. $1\frac{3}{4}^\circ$ E., $131\frac{1}{2}$ lks. dist., no marks remain.

A fir, 7 ins. diam., bears N. 76° E., 32 lks. dist., with fragmentary scribe marks visible on partially healed blaze.