

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 6 W.

CHAINS

T 30 S R 6 W
 $\frac{1}{4}$ S 7
 $\frac{1}{4}$ S 18
 1964

from which a new bearing tree

A fir, 23 ins. diam., bears S. 56° E., 58 lks.
 dist., mkd. $\frac{1}{4}$ S18 BT.

S. 89° 55' W., beginning new measurement.

Descend 195 ft. over NW. slope.

- 6.40 Creek, 1 lk. wide, course S. 75° W.; desc. 135 ft. over broken SW. slope.
- 14.30 Same creek, 2 lks. wide, course N. 75° W., desc. 140 ft. over broken NW. slope.
- 31.05 Creek, 3 lks. wide, course S. 65° W.; asc. 100 ft. over broken SE. slope.
- 40.25 Ravine, drains S. 40° E.; asc. 15 ft. over SE. slope.
- 41.54 The cor. of secs. 7, 12, 13, and 18, on the W. bdy. of the Tp.

Land, mountainous.
 Soil, rocky clay loam.
 Timber, fir, white fir, pine, cedar, madrone, oak, maple, and chinquapin; undergrowth, fern, salal, vine maple, hazel, ocean spray, poison oak, Oregon grape, and blackberry.

From the cor. of secs. 7, 8, 17, and 18.

N. 0° 53' W., bet. secs. 7 and 8.

Descend 100 ft. over NW. slope, along E. edge of logged area, through heavy timber and dense undergrowth.

- 5.70 Draw, drains N. 60° W.; asc. 25 ft. over SW. slope.
- 18.00 Spur, slopes N. 20° W.; desc. 370 ft. over broken NE. slope, changing to N. slope.
- 40.31 The $\frac{1}{4}$ sec. cor. of secs. 7 and 8, determined at record bearing and distance from the original bearing trees:
- A fir snag, 30 ins. diam., bears N. 40° E., 14 lks. dist., with scribe marks $\frac{1}{4}$ S visible on opened blaze.
- A large stump hole, bears S. 75° W., 33 lks. dist., with nothing remaining of the tree.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$
 S 7 | S 8
 T 30 S R 6 W
 1963