

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 6 W.

CHAINS

from which new bearing trees

A white fir, 12 ins. diam., bears N. 80° E., 55 lks. dist., mkd.  $\frac{1}{4}$  S8 BT, on the overgrowth of a previous blaze.

A yew, 10 ins. diam., bears N. 29 $\frac{1}{2}$ ° W., 25 lks. dist., mkd.  $\frac{1}{4}$  S7 BT.

From this point, a point established by John H. Markham, Jr., in 1955, bears East, 0.42 chs. dist., monumented with an iron pipe,  $\frac{1}{2}$  ins. diam., protruding 10 ins. above ground, from which trees marked by Markham:

A white fir, 12 ins. diam., bears N. 55° E., 17 lks. dist., with a healed blaze. (Remarked  $\frac{1}{4}$  S8 BT, as described above.)

A down fir, 14 ins. diam., bears S. 33° W., 12 lks. dist., with a healed blaze.

---

N. 1° 12' E., beginning new measurement.

Descend 45 ft. over broken N. slope.

3.90 Creek, 1 lk. wide, course N. 30° W., desc. 25 ft. over N. slope.

9.30 Same creek, 1 lk. wide, course N. 30° E.; desc. 120 ft. over N. slope, changing to NW. slope.

21.80 Draw, drains N. 60° W.; asc. 20 ft. over SW. slope.

24.80 Top of ascent, slopes NW.; desc. 150 ft. over broken NE. slope.

37.85 Dirt road, 15 lks. wide, bears N. 20° W. and S. 20° E.

40.15 The cor. of secs. 5, 6, 7, and 8, determined at record bearing and distance from the remaining original bearing tree:

A fir, 12 ins. diam., bears S. 45° W., 75 lks. dist., with scribe marks T30 visible on opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 30 S R 6 W  
 S 6 | S 5  
 S 7 | S 8  
 1963

from which new bearing trees

A sawed fir stump, 12 ins. diam., bears N. 85° E., 78 lks. dist., mkd. T30S R6W S5 BT.

A cedar, 8 ins. diam., bears S. 14° E., 35 lks. dist., mkd. T30S R6W S8 BT.

A cedar, 9 ins. diam., bears S. 51 $\frac{1}{2}$ ° W., 23 lks. dist., mkd. T30S R6W S7 BT.