

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 6 W.

CHAINS

A fir, 10 ins. diam., bears N. 87° W., 112 lks. dist., mkd. T30S R6W S6 BT.

From this point an iron pipe, $\frac{1}{2}$ ins. diam., 8 ins. above ground, firmly set, bears S. 50° W., 0.31 chs. dist., established by persons unknown.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, white fir, pine, cedar, yew, madrone, oak, maple, and chinquapin; undergrowth, fern, salal, vine maple, Oregon grape, ocean spray, hazel, and blackberry.

S. 89° 34' W., bet. secs. 6 and 7.

Ascend 35 ft. over NE. slope, along the S. edge of logged area, through heavy timber and dense undergrowth.

- 0.90 Dirt road, 15 lks. wide, bears NW. and S. 20° E.
- 4.00 Top of ascent, slopes N.; desc. 25 ft. over NW. slope.
- 6.00 Ravine, drains N. 20° W.; asc. 310 ft. over broken NE. slope.
- 30.70 Spur, slopes N. 20° W.; desc. 235 ft. over NW. slope.
- 39.64 Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 7, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 30 S R 6 W
 $\frac{1}{4}$ $\frac{S 6}{S 7}$
 1964

from which

A fir, 16 ins. diam., bears N. $11\frac{1}{2}$ ° W., 118 lks. dist., mkd. $\frac{1}{4}$ S6 BT.

A white fir, 10 ins. diam., bears S. 3° E., 115 lks. dist., mkd. $\frac{1}{4}$ S7 BT.

Corner is located at the cor. of timber, logged to the north and west.

From this point, a stone 18 x 18 x 10 ins. above ground, firmly set, bears S. 79° 00' W., 1.82 chs. dist., established by persons unknown, from which local bearing trees:

A fir, 15 ins. diam., bears N. 74° E., 18 lks. dist., with mark S and other illegible marks visible on partially healed blaze, appears to have been marked with a knife about 20 years ago.

A sawed fir stump, 35 ins. diam., bears S. 20° E., 37 lks. dist., with healed blaze.