

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 7, T. 30 S., R. 6 W.

CHAINS	
35.60	Creek, 2 lks. wide, course NW.; asc. 80 ft. over SW. slope.
39.15	Point for the center $\frac{1}{4}$ sec. cor. of sec. 7, at intersection with the E. and W. center line. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 30 S R 6 W C $\frac{1}{4}$ S 7 1964 </div> from which A fir, 30 ins. diam., bears S. $71\frac{1}{2}^\circ$ E., 65 lks. dist., mkd. C $\frac{1}{4}$ S 7 BT. A cedar, 40 ins. diam., bears S. 72° W., $30\frac{1}{2}$ lks. dist., mkd. C $\frac{1}{4}$ S 7 BT. Ascend 130 ft. over SW. slope.
48.00	Spur, slopes NW.; desc. 140 ft. over N. slope.
53.65	Ravine, drains N. 30° W.; desc. 110 ft. over NW. slope.
58.20	Creek, 1 lk. wide, course W.; asc. 25 ft. over SW. slope.
59.15	Point for the center N $\frac{1}{16}$ sec. cor. of sec. 7. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd. <div style="text-align: center;"> N $\frac{1}{16}$ $\left\{ \begin{array}{l} C \\ S 7 \\ C \end{array} \right.$ 1964 </div> from which A white fir, 13 ins. diam., bears S. 55° E., $54\frac{1}{2}$ lks. dist., mkd. CN $\frac{1}{16}$ S 7 BT. A white fir, 12 ins. diam., bears N. $16\frac{1}{2}^\circ$ W., 47 lks. dist., mkd. CN $\frac{1}{16}$ S 7 BT. Corner is located at the SE. cor. of logged area. Ascend 140 ft. over SW. slope, along the E. edge of logged area, through heavy timber and dense undergrowth.
66.70	Spur, slopes SW.; desc. 135 ft. over broken NW. slope.
79.15	The $\frac{1}{4}$ sec. cor. of secs. 6 and 7. <hr/> From the $\frac{1}{4}$ sec. cor. of secs. 7 and 8. S. $89^\circ 45'$ W., on the E. and W. center line of sec. 7. Ascend 275 ft. over NE. slope, through heavy timber and dense undergrowth.