

County Surveyor's Record, Douglas County, Oregon

T. 30 S., R. 8 W.

CHAINS

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
$$\begin{array}{c} T\ 30\ S\ R\ 8\ W \\ \frac{1}{4}\ \frac{S\ 12}{S\ 13} \\ 1964 \end{array}$$

from which new bearing trees

A fir, 12 ins. diam., bears N. 53° E., 351 lks. dist., mkd. $\frac{1}{4}$ S12 BT.A fir, 7 ins. diam., bears S. 56° E., 249 lks. dist., mkd. $\frac{1}{4}$ S13 BT.

Reset iron rod alongside the iron post.

S. $88^\circ 24'$ W., bet. secs. 12 and 13, marking and blazing true line.

Ascend 20 ft. over SE. slope, across old logged area.

2.75 Dirt road, 15 lks. wide, bears NE. and SW.

11.65 Creek, 3 lks. wide, course S. 10° E.; asc. 45 ft. over SE. slope.

17.40 Spur, slopes S.; desc. 20 ft. over SW. slope.

22.30 Ravine, drains S.; asc. 65 ft. over SE. slope.

33.90 Spur, slopes S.; desc. 20 ft. over SW. slope.

39.17 The cor. of secs. 11, 12, 13, and 14, determined from the remains of the original bearing trees:

A sawed fir stump, 32 ins. diam., bears N. 44° E., 46 lks. dist., no mks. remaining. (Record distance, 44 lks.)A sawed fir stump, 28 ins. diam., bears S. 18° E., 11 lks. dist., no mks. visible on opened blaze. (Record bearing, S. 28° E.)A sawed fir stump, 36 ins. diam., bears S. 60° W., 57 lks. dist., no mks. remaining. (Record distance, 55 lks.)A down and rotted fir, 20 ins. diam., bears N. 32° W., 30 lks. dist., with scribe marks S R8W and other illegible mks. visible.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 21 ins. in the ground, with brass cap mkd.
$$\begin{array}{c} T\ 30\ S\ R\ 8\ W \\ \frac{S\ 11\ S\ 12}{S\ 14\ S\ 13} \\ 1964 \end{array}$$

from which new bearing trees

A fir, 11 ins. diam., bears N. $74\frac{3}{4}^\circ$ E., 188 lks. dist., mkd. T30S R8W S12 BT.