

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 30 S., R. 8 W.

CHAINS

- 32.95 Ravine, drains E.; asc. 65 ft. over SE. slope.
- 39.26 Point for the $\frac{1}{4}$ sec. cor. of secs. 10 and 11, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 14 ins. long, 1 in. diam., 4 ins. in drill hole in solid rock, with brass cap mkd.
- T 30 S R 8 W
S 10 | S 11
1964
- from which
- A fir, 9 ins. diam., bears S. 27° E., 61 lks. dist., mkd. $\frac{1}{4}$ S11 BT.
- A cedar, 8 ins. diam., bears N. 3 $\frac{1}{2}$ ° W., 89 lks. dist., mkd. $\frac{1}{4}$ S10 BT.
- Ascend 25 ft. over SE. slope.
- 40.40 Top of ascent, slopes E.; desc. 15 ft. along E. slope.
- 42.00 Enter along W. edge of logged area, edges bear N. and E.
- 49.90 Bottom of descent, slopes E.; asc. 100 ft. along E. slope, changing to SE. slope.
- 64.50 Leave logged area, enter heavy timber and light undergrowth, edge bears S. and E.
- 67.10 Spur, slopes E.; desc. 130 ft. over NE. slope.
- 72.95 Ridge, bears NE. and SW.; desc. 175 ft. over NW. slope.
- 77.10 Ravine, drains N. 65° E.; asc. 5 ft. over SE. slope.
- 78.52 The cor. of secs. 2, 3, 10 and 11, monumented with the original basalt stone, 18 x 16 x 10 ins., loosely set, 3 ins. in the ground, with 5 grooves on the S. and 2 grooves on the E. face, from which the remaining original bearing trees:
- A rotted maple stump, 10 ins. diam., bears S. 38° E., 47 lks. dist., with no mks. visible.
(Record, S. 47° E.)
- A rotted fir stump, 20 ins. diam., bears N. 15° W., 54 lks. dist., with no mks. visible.
- At the corner point
- Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
- T 30 S R 8 W
S 3 | S 2
S 10 | S 11
1964
- from which new bearing trees