

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 30 S., R. 8 W.

CHAINS

A cedar, 8 ins. diam., bears N. 20° E., 117 lks. dist., mkd. T30S R8W S2 BT.

A fir, 6 ins. diam., bears S. 22 $\frac{3}{4}$ ° E., 128 lks. dist., mkd. T30S R8W S11 BT.

A fir, 40 ins. diam., bears S. 45° W., 31 lks. dist., mkd. T30S R8W S10 BT.

A fir, 33 ins. diam., bears N. 53° W., 20 lks. dist., mkd. T30S R8W S3 BT.

Deposit original corner stone alongside iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, pine, cedar, hemlock, madrone, maple, alder, dogwood, yew, chinquapin and live oak; undergrowth, poison oak, salal, Oregon grape, hazel, arrowwood, manzanita, vines and ferns.

From the cor. of secs. 1, 2, 11 and 12.

S. 88° 04' W., bet. secs. 2 and 11.

Over level ground, along S. edge of logged area, through light undergrowth.

2.40 Wet ravine, drains S. 30° E.; asc. 345 ft. over broken NE. slope, changing to E. slope.

26.80 Ridge, bears N. 10° E. and S. 10° W.; desc. 170 ft. over NW. slope, changing to N. slope.

30.00 Enter heavy timber and light undergrowth, edge bears N. and S.

39.13 The $\frac{1}{4}$ sec. cor. of secs. 2 and 11, monumented with the original basalt stone, 10 x 10 x 3 ins., loosely set, 3 ins. in the ground, mkd. $\frac{1}{4}$ on the S. face, from which the remains of the original bearing trees:

A down fir, 24 ins. diam., bears N. 28° W., 39 lks. dist., with old axe mks. visible on opened blaze.

A rotted fir stump, 20 ins. diam., bears S. 31 $\frac{1}{2}$ ° E., 18 lks. dist., with scribe mks. visible on bark, detached from stump. (Record bearing, S. 38° E.)

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 30 S R 8 W

$\frac{1}{4}$ $\frac{S 2}{S 11}$

1964

from which new bearing trees

A fir, 9 ins. diam., bears N. 11 $\frac{1}{2}$ ° W., 20 lks. dist., mkd. $\frac{1}{4}$ S2 BT.