

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 11, T. 30 S., R. 8 W.

CHAINS	
	A cedar, 15 ins. diam., bears N. 69° E., 193 lks. dist., mkd. CE 1/16 S11 BT.
	A cedar, 10 ins. diam., bears S. 0 $\frac{1}{4}$ ° W., 417 lks. dist., mkd. CE 1/16 S11 BT.
	Corner falls on spur, slopes S. 25° E.
	Descend 55 ft. over SW. slope.
25.50	Ravine, drains S. 30° E.; asc. 45 ft. over NE. slope.
26.10	Dirt road, 15 lks. wide, bears N. 45° W. and S. 45° E.
28.20	Spur, slopes SE., enter timber, edge bears NW. and SE.; desc. 10 ft. over SW. slope.
29.45	Ravine, drains SE.; asc. 215 ft. over NE. slope, changing to E. slope.
34.60	Spur, slopes S.; desc. 40 ft. over SW. slope.
38.72	The center $\frac{1}{4}$ sec. cor. of sec. 11. Descend 295 ft. over SW. slope.
54.80	Dirt road, 20 lks. wide, bears N. 30° W. and S. 40° E., in curve.
59.45	Creek, 1lk. wide, course S.; asc. 650 ft. over E. slope.
78.20	The $\frac{1}{4}$ sec. cor. of secs. 10 and 11.
	From the E 1/16 sec. cor. of secs. 11 and 14. N. 0° 27' E., on the N. and S. center line of the SE $\frac{1}{4}$ of sec. 11. Ascend 105 ft. over SE. slope, through scattering timber and dense undergrowth.
14.25	Creek, 1 lk. wide, course S. 10° E., also dirt road, 15 lks. wide, bears N. 80° W. and S. 80° E.; asc. 75 ft. over SW. slope.
19.76	Point for the SE 1/16 sec. cor. of sec. 11, at intersection with the E. and W. center line of the SE $\frac{1}{4}$. Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: right;"> Fd. BC + 1 BT MKD 2 new BTs 7/2016 C.S. 65/93-19 by D. Edwards </div>
	from which
	A fir, 22 ins. diam., bears N. 16 $\frac{1}{4}$ ° E., 100 lks. dist., mkd. SE 1/16 S11 BT.
	A fir, 10 ins. diam., bears S. 10 $\frac{3}{4}$ ° W., 91 lks. dist., mkd. SE 1/16 S11 BT.
	Ascend 330 ft. over SW. slope.
35.35	Enter logged area, edge bears N. 60° E. and S. 60° W.