

County Surveyor's Record, Douglas County, Oregon

T. 30 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

Deposit the original stone alongside the brass tablet.

No new bearing trees were mkd.

GENERAL DESCRIPTION

The lands included in the notes of the foregoing survey are located near the head of Olalla Creek approximately 9 miles south of Tenmile, Oregon. Elevations range from 2,700 feet above sea level near the southeast corner of section 15 to 1,300 feet above sea level at the $\frac{1}{4}$ section corner of sections 12 and 13. The area is mountainous with soil consisting of rocky clay at higher elevations and loam in the bottom lands along Olalla Creek.

Drainage is via small streams into Olalla Creek. Access is gained to the area from Highway No. 42 approximately 3 miles east of Tenmile, on a paved road for about 7 miles and the remainder of the way is gravel road. No habitation was noted in the area.

Timber consists chiefly of Douglas fir with stands of white fir, pine, hemlock, cedar, madrone, dogwood, alder, maple, chinquapin, yew and live oak. The undergrowth is mainly salal, hazel, manzanita, Oregon grape, arrowwood, live oak, poison oak, vine maple, huckleberry, ferns and vines. The land is being logged at the present time.

No mineral deposits were noted along the lines resurveyed.

The average of a considerable number of readings along the lines resurveyed gives a value of $19^{\circ} 30'$ E. in mean magnetic declination. There is a range of $1^{\circ} 30'$ in local attraction.