

## County Surveyor's Record, Douglas County, Oregon

T. 30 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

A fir, 18 ins. diam., bears S. 71° W., 33 lks. dist.,  
mkd.  $\frac{1}{4}$  S29 BT.

The cor. of secs. 20, 21, 28 and 29, monumented with an unmarked sandstone boulder, 16 x 8 x 6 ins., lying loose on top of a sandstone boulder and outcropping, 6 x 6 x 4 ft., from which the original bearing trees;

A fir, 21 ins. diam., bears N. 80° E., 44 lks. dist.,  
mkd. with illegible bark scribing. Reblazed and  
marked T30S R8W S21 BT.

A fir, 18 ins. diam., bears S. 74° E., 35 lks. dist.,  
mkd. T30 R8W 28 B, on a good bark blaze.

A fir, 25 ins. diam., bears S. 58° W., 54 lks. dist.,  
mkd. T30 R8W 29, on a bark blaze. Reblazed and  
marked T30S R8W S29 BT.

A live oak, 9 ins. diam., bears N. 86° W., 40 lks.  
dist., mkd. with a nearly healed blaze.

At the corner point

Set an iron pipe, 8 in. long, 1 in. diam., 7 ins. in a drilled hole in the sandstone boulder and outcropping, with a brass tablet,  $3\frac{1}{4}$  ins. diam.,  $3\frac{1}{2}$  ins. stem, driven into the iron pipe, with top marked

T 30 S.		R 8 W	
S 20		S 21	
S 29		S 28	
1963			

Deposit the original stone alongside the brass tablet.

No new bearing trees were marked.

## GENERAL DESCRIPTION

The lands included in the notes of the foregoing survey are located near the head of Olalla Creek approximately 9 miles south of Tenmile, Oregon. Elevations range from 2,700 feet above sea level near the southeast corner of section 15 to 1,300 feet above sea level at the  $\frac{1}{4}$  section corner of sections 12 and 13. The area is mountainous with soil consisting of rocky clay at higher elevations and loam in the bottom lands along Olalla Creek.

Drainage is via small streams into Olalla Creek. Access is gained to the area from Highway No. 42 approximately 3 miles east of Tenmile, on a paved road for about 7 miles and the remainder of the way is gravel road. No habitation was noted in the area.

Timber consists chiefly of Douglas fir with stands of white fir, pine, hemlock, cedar, madrone, dogwood, alder, maple, chinquapin, yew and live oak. The undergrowth is mainly salal, hazel, manzanita, Oregon grape, arrowwood, live oak, poison oak, vine maple, huckleberry, ferns and vines. The land is being logged at the present.