

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of Subdivisional Lines,
T. 31 S., R. 7 W.

CHAINS

A madrone, 30 ins. diam., bears S. 33° E., 54 lks. dist., mkd. T31S in negative on overgrowth; center of tree has rotted away.

A rotted fir stump, 45 ins. diam., bears S. 85° W., 20 lks. dist., with no mks. remaining.

A rotted fir stump, 38 ins. diam., bears N. 15° W., 10 lks. dist., with no mks. remaining.
(Record distance, 14 lks.)

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 31 S R 7 W
S 27 S 26
S 34 S 35
1964

Reset the iron pipe alongside the iron post.

Land, mountainous.

Soil, rocky clay.

Timber, pine, fir, hemlock, cedar, maple, madrone, yew, alder, live oak, and chinquapin; undergrowth, salal, arrowwood, Oregon grape, huckleberry, live oak, manzanita, young fir, whitethorn, vine maple, hazel, vines, and ferns.

From the cor. of secs. 25, 26, 35, and 36.

S. 89° 42' W., bet. secs. 26 and 35.

Ascend 125 ft. over SE. slope, through heavy timber and dense undergrowth.

15.65 Spur, slopes S. 10° W.; desc. 70 ft. over SW. slope.

18.60 Creek, 1 lk. wide, course S. 20° E.; asc. 30 ft. over SE. slope.

19.905 Point for the E 1/16 sec. cor. of secs. 26 and 35.

Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

E 1/16	S 26
	S 35
	1964

from which

A fir, 15 ins. diam., bears North, 4 lks. dist., mkd. E 1/16 S26 BT.

A fir, 20 ins. diam., bears S. 39° W., 48 lks. dist., mkd. E 1/16 S35 BT.

Ascend 85 ft. over broken SE. slope.

30.90 Spur, slopes S.; desc. 35 ft. over SW. slope.

33.95 Draw, drains S.; asc. 45 ft. over SE. slope.

36.10 Spur, slopes S.; desc. 75 ft. over SW. slope.