

13812 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of Subdivisional Lines,
T. 31 S. R. 7 W.

CHAINS

- 14.80 Creek, 2 lks. wide, course S. 35° W.; asc. 275 ft. over SE. slope.
- 28.05 Spur, slopes S. 20° W.; desc. 225 ft. over W. slope.
- 35.20 Draw, drains S.; asc. 55 ft. over E. slope.
- 37.30 Spur, slopes S.; desc. 10 ft. over W. slope.
- 39.68 The cor. of secs. 29, 30, 31, and 32, recorded and remonumented in 1963 by James W. Byron, Deputy County Surveyor, with an iron post, 1½ ins. diam., 16 ins. above ground, firmly set, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 31 S
S 30 | S 29 R
S 31 | S 32 W
1963

from which the original bearing trees:

- A live oak snag, 7 ins. diam., bears N. 66° E., 27 lks. dist., with no mks. visible on old blaze.
- A fir, 17 ins. diam., bears S. 58° E., 14 lks. dist., mkd. S32 on bark blaze.
- A madrone snag, 14 ins. diam., bears S. 81° W., 43 lks. dist., mkd. T31S R on rotting blaze.
- A cedar, 22 ins. diam., bears N. 38° W., 55½ lks. dist., mkd. with healed blaze and cruiser mks. (Record distance, 54 lks.)

and bearing trees mkd. by Byron:

- A live oak, 10 ins. diam., bears N. 63° E., 24 lks. dist., mkd. T31S R7W S29 CS BT on healed double blaze.
- A fir, 7 ins. diam., bears S. 60½° W., 52 lks. dist., mkd. T31S R7W S31 CS BT on double blaze.

Land, mountainous.

Soil, rocky clay.

Timber, fir, pine, cedar, madrone, live oak, chinquapin, and yew; undergrowth, young timber, salal, huckleberry, arrowwood, vine maple, manzanita, poison oak, vines, and ferns.

From the cor. of secs. 20, 21, 28, and 29.

S. 89° 22' W., bet. secs. 20 and 29.

Ascend 235 ft. over broken SE. slope, through heavy timber and dense undergrowth.

16.15 Blazed trail, bears N. and S.

19.70 Ridge, bears N. 30° E. and S. 30° W.; desc. 400 ft. over NW. slope.