

County Surveyor's Record, Douglas County, Oregon

T. 26 S., R. 7 W.

CHAINS

The following field notes describe the remonumentation of certain original corner points in Township 26 South, Range 7 West, of the Willamette Meridian, Oregon, as provided for in the General Special Inst., Group No. 350, Oregon, dated May 3, 1957, "Inv. of Collateral or Physical Evidence of Cor. Positions and Accessories Followed by Remonumentation of Corner Points, with New Access. When Needed".

The remonumentation of original corner points was made at the request of the Roseburg District Manager for administrative purposes of the B. L. M.

(Remonumenting the corners established by
Dennis Hathorn, in 1855)

The cor. of secs. 9, 10 15 and 16 was perpetuated and recorded by Steward in 1922, and again in 1963, by Deputy County Surveyor, Milo E. Godfrey, monumented with an iron pipe, 1 in. diam., firmly set, protruding 3 ins. above the ground, from which the only remaining original bearing tree:

A sawed fir stump, 33 ins. diam., bears N. 78° E.,
15 lks. dist., with a healed blaze.

And Steward's bearing tree

A fir, 48 ins. diam., bears S. 18½° E., 44 lks. dist.
mkd. T26S R7W S15 CS BT

and bearing trees by Godfrey

A fir, 28 ins. diam., bears N. 59° E., 7 1 lks. dist.
mkd. T26S R7W S10 CS BT.

A fir, 28 ins. diam., bears S. 89° W., 37 lks. dist.,
mkd. T26S R7W S16 CS BT.

A fir, 8 ins. diam., bears N. 48° W., 11 lks. dist.,
mkd. T26S R7W S9 CS BT.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in
the ground, with brass cap marked

T 26 S R 7 W
S 9 | S 10
S 16 | S 15
1963

FD OK PER M106-25
BY PIESKE 5-88

Reset 1 in. iron pipe alongside iron post.

The ¼ sec. cor. of secs. 9 and 10, determined at record bearing
and distance from the only remaining original bearing tree:

A down Cedar, 24 ins. diam., bears S. 67° W., 26 lks.
dist., mkd. ¼ in negative on the overgrowth.

At the corner point