

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, 5th Stan. Par. S., N. Bdy. of T. 23 S., R. 8 W.

CHAINS

S 3	S 2
T 23 S	R 8 W
S C	
1964	

Land, rolling.  
Soil, sandy clay loam.  
Timber, oak, fir, maple, alder, and cedar; undergrowth,  
vine maple, hazel, arrowwood, salal, blackberry, willow,  
poison oak, and fern.

Dependent Resurvey of a Portion of the South Boundary  
of T. 22 S., R. 8 W.  
(Restoring the 1881 survey by William H. Byars)

From the  $\frac{1}{4}$  sec. cor. of sec. 32 only, on the S. bdy. of  
T. 22 S., R. 8 W., monumented with an iron post,  $2\frac{1}{2}$  ins.  
diam., 4 ins. above ground, firmly set, marked and wit-  
nessed as described in the official record of the 1962  
resurvey by Floyd A. Brooks.

N.  $89^{\circ} 37' W.$ , along the S. bdy. of sec. 32.

Descend 250 ft. over broken W. slope, through heavy tim-  
ber and dense undergrowth.

8.50 Sawyer Creek, 6 lks. wide, course N.; asc. 230 ft. over  
broken SE. slope.

19.63 Point for the W  $1/16$  sec. cor. of sec. 32 only.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins.  
in the ground, with brass cap marked

W $1/16$ S32
1963

from which

A fir, 38 ins. diam., bears N.  $47^{\circ} E.$ , 125 lks.  
dist., mkd. W  $1/16$  S32 BT.

A maple, 12 ins. diam., bears N.  $63^{\circ} W.$ , 35 lks.  
dist., mkd. W  $1/16$  S32 BT.

Ascend 100 ft. over broken SE. slope.

32.20 Spur, slopes S.; desc. 60 ft. over broken SW. slope.

36.05 Branch, 1 lk. wide, course S.  $10^{\circ} W.$ ; asc. 35 ft. over  
broken SE. slope.

37.78 The closing cor. of secs. 5 and 6, T. 23 S., R. 8 W.,  
remonumented by the County Surveyor in 1963, with an iron  
post,  $1\frac{1}{2}$  ins. diam., 6 ins. above ground, firmly set,  
with brass cap marked

COUNTY SURVEYORS OFFICE

T22S

CC

S6	S5
T23S	R8W
1963	

from which the original bearing trees, mkd. by Whipple  
in 1894: