

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the E. Bdy. of T. 22 S., R. 8 W.

CHAINS
40.48

The $\frac{1}{4}$ sec. cor. of secs. 25 and 30, remonumented by the County Surveyor, in 1961, with an iron post, $1\frac{1}{2}$ ins. diam., 14 ins. above ground, firmly set, with brass cap marked

COUNTY SURVEYORS OFFICE

T22S
S25|S30
 $\frac{1}{4}$
1961

from which the original bearing trees:

A white oak, 25 ins. diam., bears N. $31\frac{1}{2}^{\circ}$ E., 51 lks. dist., with no marks remaining on opened blaze.

A white oak, 30 ins. diam., bears N. 58° W., 100 lks. dist., with no marks remaining on opened blaze.

and bearing trees marked by the County Surveyor:

A white oak, 18 ins. diam., bears S. $33\frac{3}{4}^{\circ}$ E., 55 lks. dist., with scribe marks $\frac{1}{4}$ S30 CS BT visible on partly healed blaze.

A white oak, 13 ins. diam., bears S. $79\frac{1}{4}^{\circ}$ W., 24 lks. dist., with scribe marks $\frac{1}{4}$ S25 CS BT visible on partly healed double blaze.

The cor. is located at a corner of woven-wire fences, which extend N. and W.

N. $0^{\circ} 55'$ W., beginning new measurement.

Ascend 10 ft. over S. slope, through thin second-growth timber and dense undergrowth.

1.20 Spur ridge, bears E. and W.; desc. 410 ft. over NE. slope.

19.60 Branch, 10 lks. wide, course E.; asc. 200 ft. over SE. slope, along W. edge of cleared land.

30.15 Spur, slopes E.; desc. 50 ft. over NE. slope.

39.40 The cor. of secs. 19, 24, 25, and 30, determined at record bearing and distance from the remaining bearing trees:

A sawed fir stump, 60 ins. diam., bears N. 49° E., 60 lks. dist., with fragmentary scribe marks visible on opened blaze.

A burned and decayed fir stump, size indeterminate, bears S. 26° W., 170 lks. dist., with no marks remaining.

A sawed fir stump, 42 ins. diam., bears N. 11° W., 70 lks. dist., with no marks remaining.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked