

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the S. Bdy. of T. 21 S., R. 8 W.

## CHAINS

- 13.90 The true point for the closing cor. of secs. 4 and 5, T. 22 S., R. 8 W., hereinafter described; asc. 250 ft. over broken SE. slope.
- 25.85 Dirt road, 25 lks. wide, bears N. and S.; enter logged area, edge bears same as road.
- 27.80 Spur, slopes S.; desc. 26 ft. over general W. slope.
- 35.35 Ridge, divide bet. Weatherly Creek and the Umpqua River, bears N. 70° E. and S. 70° W.; desc. 45 ft. over NW. slope.
- 39.46 The  $\frac{1}{4}$  sec. cor. of sec. 32 only, monumented with an iron post, 1 in. diam., 10 ins. above ground, firmly set, with brass cap marked

 $\frac{1}{4}$  S32

1945

from which an original bearing tree,

A sawed fir stump, 50 ins. diam., bears S. 73° E., 50 lks. dist., with only bottom of blaze remaining.

and bearing trees marked by Price:

A sawed fir stump, 40 ins. diam., bears N. 56 $\frac{1}{4}$ ° E., 186 lks. dist., with fragmentary scribe marks visible on open and burned blaze.

A down fir, 35 ins. diam., bears N. 87 $\frac{1}{2}$ ° E., 222 lks. dist., with fragmentary scribe marks visible on open and burned blaze.

and a new bearing tree,

A burned fir snag, 36 ins. diam., bears N. 29 $\frac{3}{4}$ ° E., 141 lks. dist., mkd.  $\frac{1}{4}$  S32 BT.

Set a 7 ft. steel fence post, 2 ft. in the ground alongside the iron post.

Cor. is located about one chain N. of ridge.

S. 89° 22' W., beginning new measurement.

Descend 3 ft. over NW. slope.

- 0.10 Head of ravine, drains N. 30° W.; asc. 27 ft. over NE. slope.
- 3.80 Spur, slopes N. 25° W.; desc. 175 ft. over broken SW. slope.
- 14.95 Dirt road, 20 lks. wide, bears N. and S.
- 15.94 Point for the  $\frac{1}{4}$  sec. cor. of sec. 5, T. 22 S., R. 8 W., at midpoint in departure on the N. bdy. of sec. 5.
- Set an iron post, 28 ins. long, 2 $\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

$\frac{1}{4}$  S5  
T22S R8W  
1963