

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion Subdivisional Lines, T. 22 S., R. 8 W.

CHAINS

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

$$\frac{1}{4} \frac{S 16}{S 21}$$

T 22 S R 8 W
1963

from which

A fir, 10 ins. diam., bears N. $26\frac{1}{4}^\circ$ E., $58\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S16 BT.

A fir, 12 ins. diam., bears S. $54\frac{1}{2}^\circ$ E., 100 lks. dist., mkd. $\frac{1}{4}$ S21 BT.

N. $0^\circ 02'$ E., bet. secs. 16 and 17.

Descend slightly across pasture land.

- 15.35 Woven wire fence, bears N. 30° E. and S. 30° W.
- 16.35 Henderer Road, gravelled, 25 lks. wide, bears N. 30° E. and S. 30° W.
- 17.15 Leave pasture land; edge bears N. 30° E. and S. 30° W.; asc. 65 ft. over SE. slope, through scattering timber and dense undergrowth.
- 17.35 Woven wire fence, bears N. 30° E. and S. 30° W.
- 25.60 Enter open field, edge bears E. and W.
- 33.25 Top of ascent, slopes E. also edge of field and woven wire fence, bears E. and W.; desc. 6 ft. over NE. slope.
- 40.44 Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

$$S 17 \frac{1}{4} S 16$$

T 22 S R 8 W
1963

from which

An oak, 42 ins. diam., bears S. 69° E., 44 lks. dist., mkd. $\frac{1}{4}$ S16 BT.

A fir, 8 ins. diam., bears S. 78° W., 15 lks. dist., mkd. $\frac{1}{4}$ S17 BT.

Descend 3 ft. over NE. slope.

- 42.05 Creek, 4 lks. wide, course S. 60° E.; asc. 60 ft. over SE. slope.
- 45.95 Woven wire fence, bears N. 65° W. and S. 65° E.; thence across open field.
- 51.40 Woven wire fence, bears N. 15° E. and S. 15° W.; enter scattering timber and dense undergrowth, edge bears same as fence.
- 54.85 Creek, 2 lks. wide, course S. 15° E.; asc. 13 ft. over SE. slope.