

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion Subdivisional Lines, T. 22 S., R. 8 W.

CHAINS	
	<p>From the cor. of secs. 31 and 32, on the S. bdy. of Tp., heretofore described.</p> <p>N. 1° 10' E., bet. secs. 31 and 32.</p> <p>Ascend 260 ft. over SE. slope, through heavy timber and dense undergrowth.</p>
19.95	Gravel road, 25 lks. wide, bears N. 50° E. and S. 50° W.
20.15	<p>Point for the S 1/16 sec. cor. of secs. 31 and 32.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked</p> <p style="text-align: center;">S 1/16 S 31 S 32 1963</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 5 ins. diam., bears S. 61½° E., 93½ lks. dist., mkd. S 1/16 S32 BT.</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears N. 27½° W., 39 lks. dist., mkd. S1/16 S31 BT.</p> <p>Ascend 30 ft. over broken SE. slope.</p>
29.05	Spur, slopes NE.; desc. 210 ft. over N. slope.
31.55	Same gravel road, bears E. and W.
33.70	Creek, 2 lks. wide, course N. 65° E.; asc. 100 ft. over SE. slope.
40.30	<p>The ¼ sec. cor. of secs. 31 and 32, monumented with an iron post, 2½ ins. diam., 4 ins. above ground, firmly set, mkd. and witnessed as described in the official record of the 1960 resurvey.</p> <p>Land, mountainous. Soil, rocky and sandy. Timber, fir, hemlock, cedar, maple, oak, alder, madrone, and cascara; undergrowth, fern, hazel, poison oak, salal, and bunch grass.</p>
	<p>From the cor. of secs. 16, 17, 20, and 21.</p> <p>N. 86° 35' W., bet. secs. 17 and 20.</p> <p>Descend slightly across open pasture land.</p>
7.25	Woven wire fence, bears N. 30° E. and S. 30° W.
7.29	<p>Point for a witness point on line bet. secs. 17 and 20.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 21 ins. in the ground, with brass cap marked</p> <p style="text-align: center;">WP $\frac{S 17}{S 20}$ 1963</p>
7.40	Henderer Road, graveled, 25 lks. wide, bears N. 30° E. and S. 30° W.
7.65	Woven wire fence, bears N. 30° E. and S. 30° W.