

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion Subdivisional Lines, T. 22 S., R. 8 W.

CHAINS	
5.10	Spur, slopes W.; enter heavy timber, edge bears E. and W.; desc. 460 ft. over broken NW. slope.
20.25	Spur, slopes N. 20° W., desc. 310 ft. over NE. slope.
33.90	Creek, 3 lks. wide, course N. 40° W.; asc. 120 ft. over SW. slope.
38.11	The cor. of secs. 7, 8, 17, and 18, monumented with an iron post, 2 ins. diam., 8 ins. above ground, firmly set, mkd. and witnessed as described in the official record of the 1931 resurvey by Rigby.
	Land, mountainous. Soil, sandy and rocky. Timber, fir, hemlock, cedar, maple, oak, madrone, alder, and cascara; undergrowth, fern, salal, poison oak, hazel, and Oregon grape.
	From the cor. of secs. 8, 9, 16, and 17. N. 89° 47' W., bet. secs. 8 and 17. Ascend 210 ft. over broken SE. slope, through heavy timber and dense undergrowth.
7.45	Dirt road, 15 lks. wide, bears N. and S.
21.10	Creek, 1 lk. wide, course S. 30° E.; asc. 200 ft. over SE. slope.
33.70	Ridge and skid road, 15 lks. wide, bear N. 30° E. and S. 30° W.; desc. 268 ft. over broken NW. slope.
40.45	Dry creek bed, 2 lks. wide, course N. 60° W.; desc. 7 ft. along N. slope.
41.265	Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 17, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked $\frac{1}{4} \frac{S 8}{S 17}$ T 22 S R 8 W 1963
	from which A fir, 55 ins. diam., bears N. 62° E., 112 lks. dist., mkd. $\frac{1}{4}$ S8 BT. A maple, 25 ins. diam., bears S. 48 $\frac{1}{2}$ ° E., 37 lks. dist., mkd. $\frac{1}{4}$ S17 BT.
	Ascend 50 ft. over NE. slope.
43.95	Spur, slopes N.; desc. 130 ft. over NW. slope.
48.90	Ravine, drains NW.; asc. 40 ft. over NE. slope.
50.70	Spur, slopes N.; desc. 230 ft. over broken W. slope.
65.15	Creek, 3 lks. wide, course W.; desc. 16 ft. along creek bottom.