

County Surveyor's Record, Douglas County, Oregon

Resurvey of Boundaries, Claim No. 49, T. 22 S., R. 8 W.

CHAINS	
171.09	Point for closing cor. at intersection with the E. and W. center line of the NW $\frac{1}{4}$ of sec. 5, hereinafter described.
172.06	Point for closing cor. at intersection with the N. and S. center line of sec. 5, hereinafter described.
175.42	Point for the N. cor. of Claim No. 49, determined by the method of broken boundaries; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked T 22 S R 8 W S 5 / \ C 49 / \ 1963 from which A fir, 34 ins. diam., bears N. 34° E., 55 lks. dist., mkd. T22S R8W S5 BT. A fir, 5 ins. diam., bears S. 14° W., 7 lks. dist., mkd. T22S R8W C49 BT.
	S. 40° 44' E., on a blank line along the NE. bdy. of Claim No. 49.
30.36	Point for closing cor. at intersection with the E. and W. center line of sec. 5, hereinafter described.
51.30	Find no evidence of the oak tree mentioned by Hathorn as being on line at 51.33 chs.
52.61	Point for witness meander cor. of the NE. bdy. of Claim No. 49. Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked T 22 S R 8 W W C / \ C 49 S 5 / \ M C 1963 from which A white oak, 23 ins. diam., bears N. 30° E., 16 lks. dist., mkd. X BT. No other suitable bearing tree available.
53.40	Enter the Umpqua River, course S. 60° W.
53.97	True point for the meander cor. of the NE. bdy. of Claim No. 49, falls in river, where it is impracticable to establish a permanent monument. Hathorn's notes do not describe establishment of a meander corner, this being the proportionate distance to where he reached the river.
57.74	Intersect the line bet. secs. 4 and 5. Point falls in river.
62.50	Leave river; asc. 13 ft. over bank.