

## County Surveyor's Record, Douglas County, Oregon

Resurvey of Boundaries of Claim No. 54, T. 22 S., R. 8 W.

CHAINS

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked
$$\begin{array}{r} T\ 22\ S\ R\ 8\ W \\ C\ 54 \\ \hline S\ 34 \\ 1964 \end{array}$$

from which new bearing trees:

An oak, 15 ins. diam., bears S.  $81^\circ$  W., 16 lks. dist., mkd. T22S R8W S34 BT.A fir, 7 ins. diam., bears N.  $44^\circ$  W., 86 lks. dist., mkd. T22S R8W C54 BT.S.  $89^\circ 59'$  W., on a blank line along the S. bdy. of Claim No. 54.

29.26 Point for the closing cor. at intersection with the line bet. secs. 33 and 34.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked
$$\begin{array}{r} C\ 54 \\ S\ 33\ | \ S\ 34 \\ \hline C\ C \\ T\ 22\ S\ R\ 8\ W \\ 1964 \end{array}$$

from which

A fir, 6 ins. diam., bears S.  $8^\circ$  E., 63 lks. dist., mkd. T22S R8W S34 CC BT.A fir, 10 ins. diam., bears S.  $18^\circ$  W., 96 lks. dist., mkd. T22S R8W S33 CC BT.From this point the cor. of secs. 27, 28, 33, and 34, bears N.  $0^\circ 46'$  E., 19.93 chs. dist.

52.21 The SW. cor. of Claim No. 54, monumented with the remains of the original cor. tree; a decayed hemlock stump, 24 ins. diam., with no marks remaining, from which the original bearing trees:

A cedar, 40 ins. diam., bears N.  $9^\circ$  E., 142 lks. dist., with no marks visible on opened blaze. (Record distance, 135 lks.)A down cedar, 48 ins. diam., bears N.  $55^\circ$  W., 37 lks. dist., with fragmentary scribe marks visible on burned face of blaze.

At the corner point through the decayed stump,

Set an iron post, 36 ins. long, 1 in. diam., 34 ins. in the ground in center of stump, with brass cap marked

$$\begin{array}{r} T\ 22\ S\ R\ 8\ W \\ S\ 33\ | \ C\ 54 \\ \hline 1964 \end{array}$$

from which new bearing trees: