

# County Surveyor's Record, Douglas County, Oregon

## Subdivision of Section 27, T. 22 S., R. 8 W.

CHAINS  
39.76

The N 1/16 sec. cor. of secs. 27 and 28.

## Subdivision of Section 32, T. 22 S., R. 8 W.

From the  $\frac{1}{4}$  sec. cor. of sec. 32 only, on the S. bdy. of the Tp., heretofore described.

N.  $0^{\circ} 44'$  E., on the N. and S. center line of sec. 32.

Descend 130 ft. over NW. slope, through heavy timber and dense undergrowth.

4.50 Ravine, drains S.  $70^{\circ}$  W.; asc. 260 ft. over SW. slope.

20.115 Point for the center S 1/16 sec. cor. of sec. 32.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

C  
S 1/16 | S 32  
C  
1964

from which

A fir, 10 ins. diam., bears S.  $87^{\circ}$  E., 76 lks. dist., mkd. CS 1/16 S32 BT.

A fir, 30 ins. diam., bears N.  $36\frac{1}{2}^{\circ}$  W., 27 lks. dist., mkd. CS 1/16 S32 BT.

Ascend 70 ft. over SW. slope.

29.95 Spur, slopes W.; desc. 280 ft. over NW. slope.

39.30 Ravine, drains NW.; asc. 10 ft. over SW. slope.

40.23 Point for the center  $\frac{1}{4}$  sec. cor. of sec. 32, at intersection with the E. and W. center line.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

C  $\frac{1}{4}$  S32  
1964

*Ed. O.K. by:  
K.R. LUCKMAN  
6-10-82  
M 92 54*

from which

A hemlock, 19 ins. diam., bears S.  $38^{\circ}$  E., 99 lks. dist., mkd. C  $\frac{1}{4}$  S32 BT.

A fir, 17 ins. diam., bears N.  $24\frac{1}{2}^{\circ}$  W., 99 lks. dist., mkd. C  $\frac{1}{4}$  S32 BT.

Ascend 35 ft. over SW. slope.

44.75 Spur, slopes W.; desc. 120 ft. over NW. slope.

47.20 Ravine, drains NW.; asc. 100 ft. over SW. slope.

53.10 Spur, slopes W.; desc. 170 ft. over broken NW. slope.

59.965 Point for the center N 1/16 sec. cor. of sec. 32.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked