

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of E. Bdy., T. 25 S., R. 8 W.

CHAINS

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 25 S	
R 8 W	
$\frac{1}{4}$ S 13	
	1964

from which

A cedar, 28 ins. diam., bears S.  $61^\circ$  W., 57 lks. dist., mkd.  $\frac{1}{4}$  S13 BT.

A hemlock, 12 ins. diam., bears N.  $49^\circ$  W., 54 lks. dist., mkd.  $\frac{1}{4}$  S13 BT.

Ascend 515 ft. over broken SW. slope.

65.37

Point for the closing corner of secs. 7 and 18, T. 25 S., R. 7 W., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $w\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 25 S	
R 8 W	R 7 W
S 13	$\frac{S}{S}$ $\frac{7}{18}$ 8C
	1964

from which

A fir, 54 ins. diam., bears N.  $23\frac{1}{2}^\circ$  E., 38 lks. dist., mkd. T25S R7W S7 CC BT.

A fir, 40 ins. diam., bears S.  $59^\circ$  E., 51 lks. dist., mkd. T25S R7W S18 CC BT.

The corner falls on a spur, slopes S.  $60^\circ$  W.; desc. 190 ft. over broken NW. slope.

75.30

The cor. of secs. 12 and 13 only, remonumented and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1962, with an iron pipe, 1 in. diam., 8 ins. above the ground, firmly set, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 25 S	
S 12	R
S 13	7
R8W	W
	1962

from which the remaining original bearing trees

A fir, 30 ins. diam., bears S.  $65^\circ$  E., 27 lks. dist., with scribe marks T 2 R and other illegible marks visible on bark blaze. (Marks were reported destroyed by Heydon in 1896)

A fir, 52 ins. diam., bears S.  $85^\circ$  W., 16 lks. dist., with bark blaze, no scribing visible. (Record, 12 lks.)

and bearing trees marked by Godfrey

A white fir, 14 ins. diam., bears S.  $55^\circ$  W., 35 lks. dist., with scribe marks T25S R8W S13 CS BT visible on double blaze.