

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 25 S., R. 7 W.

CHAINS	
	<p>A white fir, 27 ins. diam., bears N. 74° W., 69½ lks. dist., mkd. T25S R7W S7 BT.</p> <p>N. 89° 53' W., bet. secs. 7 and 18.</p> <p>Descend 200 ft. over broken NW. slope, through heavy timber and dense undergrowth.</p>
5.64	Creek, 3 lks. wide, course N. 20° W.; asc. 220 ft. over N.E. slope.
12.00	Spur, slopes N. 10° W.; desc. 40 ft. over NW. slope.
15.60	Draw, drains N. 20° W.; desc. 365 ft. over broken NW. slope, changing to W. slope.
37.63	<p>Point for the ¼ Sec. cor. of sec. 7 only, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set and iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T. 25 S R 7 W ¼ S 7 1964</p> <p>from which</p> <p>A fir, 32 ins. diam., bears N. 14½° E., 49 lks. dist., mkd. ¼ S7 BT.</p> <p>A hemlock, 23 ins. diam., bears N. 60° W., 79 lks. dist., mkd. ¼ S7 BT.</p> <p>Descend 65 ft. over W. slope.</p>
39.20	Creek, 5 lks. wide, course N. 10° W.; asc. 10 ft. over NE. slope.
39.46	<p>Point for the ¼ sec. cor. of sec. 18 only, at proportionate distance based on the original record.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 25 S R 7 W ¼ S 18 1964</p> <p>from which</p> <p>A hemlock, 10 ins. diam., bears S. 88½° E., 66½ lks. dist., mkd. ¼ S18 BT.</p> <p>A cedar, 8 ins. diam., bears S. 20° W., 29 lks. dist., mkd. ¼ S18 BT.</p> <p>and a bearing tree of which I have no record</p> <p>A cedar, 48 ins. diam., bears S. 36° E., 53 lks. dist., with scribe marks ¼ BT visible on partially healed blaze on N. side.</p> <p>Ascend 450 ft. over NE. slope.</p>
50.00	Spur, slopes N.; desc. 100 ft. over NW. slope.
59.19	Point for the W 1/16 sec. cor. of sec. 18 only.