

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines. T. 25 S., R. 8 W.

CHAINS

Land, mountainous.
Soil, rocky clay.
Timber, fir, hemlock, cedar, maple, madrone, alder, yew,
dogwood and chinquapn; undergrowth, salal, poison oak,
Oregon grape, hazel, vine maple, rhododendron, arrowwood,
salmonberry, vines and ferns.

N. 0° 32' E., bet. secs. 25 and 26.

Descend 510 ft. over NE. slope, through heavy timber and
dense undergrowth.

18.20 Creek, 2 lks. wide, course N. 30° W.; asc. 150 ft. over
SW. slope.

33.20 Spur, slopes NW.; desc. 295 ft. over N. slope.

39.36 The $\frac{1}{4}$ sec. cor. of secs. 25 and 26, determined at record
bearing and distance from the original NW. bearing tree:

A down fir, 35 ins. diam., bears N. 80° W., 15 lks.
dist., mkd. $\frac{1}{4}$ S on a bark blaze.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

T 25 S R 8 W
S 26 | S 25
1964

from which new bearing trees

A hemlock, 7 ins. diam., bears N. 75 $\frac{1}{2}$ ° E., 23 lks.
dist., mkd. $\frac{1}{4}$ S25 BT.

A hemlock, 8 ins. diam., bears S. 31 3/4° W., 27 lks.
dist., mkd. $\frac{1}{4}$ S26 BT.

N. 1° 28' W., beginning new measurement.

Descend 50 ft. over N. slope, through heavy timber and
light undergrowth.

0.95 Creek, 1 lk. wide, course N. 80° W.; asc. 320 ft. over
S. slope, changing to SW. slope.

13.00 Spur, slopes N. 80° W.; desc. 145 ft. over N. slope.

16.05 Ravine, drains N. 80° W., asc. 295 ft. over SW. slope.

27.35 Spur, slopes N. 60° W.; desc. 35 ft. over nearly level
NE. slope.

42.55 Point for cor. of secs. 23, 24, 25, and 26, at proportionate
distance; there is no remaining evidence of the original
corner.

Set an iron post, 28 ins. long 2 $\frac{1}{2}$ ins. diam., 23 ins. in the
ground, with brass cap mkd.

T 25 S R 8 W
S 23 | S 24
S 26 | S 25
1965