

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 25 S., R. 8 W.

CHAINS

A fir, 9 ins. diam., bears S. 52° E., 53½ lks.  
dist., with a healed double blaze.

A fir, 11 ins. diam., bears S. 23° W., 31½ lks.  
dist., with a healed double blaze.

A fir, 8 ins. diam., bears N. 48½° W., 23 lks.  
dist., with a healed double blaze.

Add the marks ELM 1965 to top of brass cap.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, maple, madrone, dogwood,  
chinquapin, alder, yew, myrtle and live oak; undergrowth,  
salal, arrowwood, Oregon grape, hazel, vine maple,  
poison oak, huckleberry, rhododendron, vines and ferns.

Remonumentation of Certain Original Corner Points  
T. 25 S., R. 8 W., Willamette Meridian, Oregon

The following field notes describe the remonumentation of certain original corner points in T. 25 S., R. 8 W., as provided for in the General Special Instructions, Group No. 350, Oregon, dated May 3, 1957, "Investigations of Collateral or Physical Evidence of Corner Positions and Accessories, Followed by Remonumentation of Corner Points, with New Accessories When Needed."

(Remonumentation of corners established by  
Morris Wygant in 1911)

The ¼ sec. cor. of sec. 3 only, on the E. bdy. of the sec., determined at record bearing and distance from the remains of the original bearing trees:

A down madrone, 14 ins. diam., bears N. 80° W.,  
30 lks. dist., with illegible scribe marks visible  
in negative on the overgrowth.

A stump hole, bears N. 46° W., 32 lks. dist.,  
the tree, a fir, 35 ins. diam., has fallen and  
slid down hill, mkd. with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.  
in the ground, with brass cap mkd.

T 25 S. R 8 W  
¼  
S 3  
1965

from which

A hemlock, 8 ins. diam., bears S. 66° W., 30 lks.  
dist., mkd. ¼ S3 BT.

A hemlock, 7 ins. diam., bears N. 60° W., 56 lks.  
dist., mkd. ¼ S3 BT.