

## County Surveyor's Record, Douglas County, Oregon

Dependant Resurvey of the W. Bdy., T. 29 S., R. 3 W.

CHAINS

67.89

Point for the cor. of secs. 19 and 30 only, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T 29 S	T 29 S
S 25	S 19
R 4 W	S 30
	R 3 W
	1964

from which

A fir, 20 ins. diam., bears N.  $53^\circ$  E., 37 lks. dist., mkd. T29S R3W S19 BT.

A cedar, 12 ins. diam., bears S.  $13\frac{3}{4}^\circ$  E., 46 lks. dist., mkd. T29S R3W S30 BT.

The corner is located at the S.W. corner of a logged area, edge bears N. & E.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, maple, madrone, yew, alder, dogwood, oak and chinquapin; undergrowth, salal, Oregon grape, poison oak, hazel, arrowwood, vines and ferns.

N.  $0^\circ 42'$  E., on the W. bdy. of sec. 19.

Descend 275 ft. over N.W. slope, along W. edge of logged area

8.32

The cor. of secs. 24 and 25 only, on the E. bdy. of T. 29 S., R. 4 W., remonumented by A. R. Evans, Deputy County Surveyor, in 1949, and rehabilitated by James W. Byron, Deputy County Surveyor, in 1962, monumented with an iron post, 1 in. diam., 6 ins. above ground, firmly set, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 29 S	R 4 W
<u>24</u>	sec.
25	cor.
	RE 2741

from which the remains of the original S.W. bearing tree

A rotted fir stump, 14 ins. diam., bears S.  $76\frac{1}{2}^\circ$  W., 15 lks. dist., with fragmentary scribe marks visible. (Record, S.  $55^\circ$  W.)

and bearing trees marked by Evans

A fir, 25 ins. diam., bears S.  $45^\circ$  E., 31 lks. dist., with a partially healed blaze.

A down fir, 25 ins. diam., bears N.  $70^\circ$  W., 23 lks. dist., mkd. T29S R4W S24 CS BT on bark blaze.

and a bearing tree marked by Byron

A fir, 7 ins. diam., bears N.  $14\frac{3}{4}^\circ$  W., 35 lks. dist., with a partially healed double blaze.

and a new bearing tree: