

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the W. Bdy., T. 29 S., R. 3 W.

CHAINS

N. 1° 28" E., beginning new measurement.

Ascend 50 ft. over S.W. slope.

- 0.13 Woven wire fence, bears E. and W.
- 3.50 Spur, slopes S. 75° E.; desc. 70 ft. over N.E. slope.
- 10.90 Ravine, drains S. 75° E.; asc. 60 ft. over S.W. slope.
- 13.45 Spur, slopes S. 70° E.; desc. 45 ft. over N.E. slope.
- 18.40 Ravine, drains S. 75° E.; asc. 70 ft. over S. E. slope.
- 21.80 Spur, slopes E.; desc. 40 ft. over N.E. slope.
- 26.95 Ravine, drains S. 75° E.; asc. 75 ft. over S.E. slope.
- 32.00 Top of ascent, slopes S. 70° E.; desc. 10 ft. over N.E. slope.
- 33.05 The cor. of secs. 18 and 19 only, remonumented and recorded by James W. Byron, Deputy County Surveyor, in 1960, with an iron post, 1 in. diam., 14 ins. above ground, firmly set, with brass cap mkd.

## COUNTY SURVEYORS OFFICE

T 29 S
S 18
S 19
R 4 W   R 3 W
1960

from which the remains of the original bearing trees

A rotted fir stump, 14 ins. diam., bears N. 10° E., 30 lks. dist., mkd. BT on opened blaze.

A fir snag, 40 ins. diam., bears S. 80° E., 28 lks. dist., with fragmentary scribe marks visible.

and bearing trees mkd. by Byron

A fir, 6 ins. diam., bears N. 76° E., 30 lks. dist., mkd. with a partially healed double blaze.

A pine, 7 ins. diam., bears S. 50½° E., 40 lks. dist., mkd. with a partially healed double blaze.

Add the marks BLM to the brass cap.

Land,, mountainous.

Soil, rocky clay, clay loam.

Timber, fir, cedar, hemlock, pine, maple madrone, yew, alder, dogwood, oak and chinquápin; undergrowth, salal, hazel, Oregon grape, arrowwood, poison oak, vine maple, blackberry, ferns and vines.

N. 1° 28' E., on the W. bdy. of sec. 18.

Descend 50 ft. over N.E. slope, through logged area and dense undergrowth.

- 4.50 Ravine, drains E.; asc. 50 ft. over S.E. slope.

- 6.19 The cor. of secs. 13 and 24 only, on the E. bdy. of T. 29 S., R. 4 W., determined at record distance from the remains of the original bearing trees: