

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the W. Bdy., T. 29 S., R. 3 W.

CHAINS

A madrone stump hole, bears N. 20° E., 10 lks. dist.
 A madrone stump hole, bears S. 65° E., 50 lks. dist.
 A madrone stump hole, bears S. 50° W., 58 lks. dist.
 A madrone stump hole, bears N. 35° W., 64 lks. dist.,
 (Record bearing by Byars, N. 5° W.)

All the stump holes have young madrone trees growing
 around the edges.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins.
in the ground, with brass cap mkd.

T 29 S	T 29 S
S 13	R 3 S
S 24	S 18
R 4 W	
1964	

from which new bearing trees

A fir, 8 ins. diam., bears S. 12° W., 62 lks.
 dist., mkd. T29S R4W S24 BT.

A fir, 6 ins. diam., bears N. 54½° W., 27 lks.
 dist., mkd. T29S R4W S13 BT.

North, beginning new measurement.

Ascend 30 ft. over S.E. slope, through dense undergrowth.
along W. edge of logged area.

- 1.45 Spur, slopes E.; desc. 85 ft. over N.E. slope.
- 6.45 Ravine, drains S. 55° E., asc. 75 ft. over S.W. slope.
- 8.85 Spur, slopes S. 70° E.; desc. 115 ft. along broken E. slope,
changing to N.E. slope.
- 27.45 Creek, 1 lk. wide, course S. 60° E.; asc. 160 ft. over
S.E. slope.
- 38.27 Point for the ¼ sec. cor. of secs. 13 and 18, restored
by the method of irregular boundaries; there is no
remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins.
in the ground, with brass cap mkd.

T 29 S	
¼	
R 4 W	R 3 W
S 13	S 18
1964	

from which

A fir, 22 ins. diam., bears S. 4¼° E., 75 lks.
 dist., mkd. ¼ S18 BT.

A fir, 25 ins. diam., bears N. 44° W., 49 lks.
 dist., mkd. ¼ S13 BT.