

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 29 S., R. 3 W.

CHAINS

T 29 S R 3 W
 S 15 | S 11
 | S 14
 1964

Reset iron rod alongside iron post.

N. 1° 48' E., on the W. bdy. of sec. 11, marking and blazing the true line.

Ascend 120 ft. over S.E. slope, along the E. edge of logged area.

- 5.00 Enter scattering timber and light undergrowth, edge bears S. and W.
- 5.70 Spur, slopes S. 50° W.; continue over spur.
- 6.11 Point for the closing corner of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 29 S |
 CC S 10 | S 11
 | S 15
 R 3 W |
 1964

from which

A fir, 10 ins. diam., bears S. 78° W., 45 lks. dist., mkd. T29S R3W S15 CC BT

A fir, 10 ins. diam., bears N. 33½° W., 29 lks. dist., mkd. T29S R3W S10 CC BT.

Descend 150 ft. over N.W. slope.

- 13.30 Ravine, drains W.; asc. 20 ft. over S.W. slope.
- 15.20 Spur, slopes W.; desc. 365 ft. over N.W. slope.
- 16.20 Enter logged area, edge bears E. and W.
- 33.65 Creek, 4 lks. wide, course N. 70° W.; asc. 10 ft. over S.W. slope.
- 34.75 Dirt road, 15 lks. wide, bears N.W., curving N., and S. 80° E.
- 34.90 Top of ascent, slopes W.; desc. 5 ft. over N.W. slope.
- 39.91 The ¼ sec. cor. of secs. 10 and 11, monumented with rotted portions of the original corner post, below the surface of the ground, from which the remains of an original bearing tree:

A rottedfir root crown, size indeterminate, bears East, 8 lks. dist.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.