

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 29 S., R. 3 W.

CHAINS	
9.60	Ravine, drains E.; asc. 10 ft. over SE. slope.
12.70	Top of ascent, slopes E.; desc. 45 ft. over NE. slope.
17.05	Lally Creek, 1 lk. wide, course S. 20° E.; asc. 165 ft. over SW. slope.
33.26	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 4, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 21 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 29 S R 3 W $\frac{1}{4}$ S 4 S 3 1964 </div> from which A fir, 12 ins. diam., bears N. $88\frac{1}{2}^\circ$ E., 98 lks. dist., mkd. $\frac{1}{4}$ S3 BT. A cedar, 15 ins. diam., bears N. 26° W., 52 lks. dist., mkd. $\frac{1}{4}$ S4 BT. Ascend 65 ft. over SW. slope.
49.50	Spur, slopes S. 80° W.; desc. 30 ft. over N. slope.
50.95	Creek, 1 lk. wide, course S. 80° W.; asc. 120 ft. over S. slope, changing to SW. slope.
56.10	Top of ascent, slopes W.; desc. 55 ft. over NW. slope.
62.35	Creek, 1 lk. wide, course S. 50° W.; asc. 190 ft. over SE. slope.
70.44	The cor. of secs. 3 and 4 only, on the N. bdy. of the Twp., heretofore described. Land, mountainous. Soil, rocky clay. Timber, fir, pine, cedar, hemlock, madrone, maple, yew, chinquapin, fir, alder, dogwood, and live oak; undergrowth, salal, poison oak, huckleberry, Oregon grape, hazel, vine maple, arrowwood, blackberry, ferns and vines.
Subdivision of Section 3, T. 29 S., R. 3 W.	
The following subdivision of section 3 was executed in conformity with legal surveying practice. The record of true line notes, only, is set forth in the following field notes.	

From the $\frac{1}{4}$ sec. cor. of secs. 3 and 10.	
N. 0° 11' E.; on the N. and S. center line of sec. 3, marking and blazing the true line.	
Descend 40 ft. over NE. slope, across logged area through dense undergrowth.	
5.65	Wet ravine, drains S. 35° E.; asc. 330 ft. over SW. slope.