

## County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 3, T. 29 S., R. 3 W.

CHAINS	
22.35	Spur, slopes S. 10° E.; asc. 115 ft. over broken SE. slope.
38.40	Enter scattering timber, edge bears E. and W.
39.48	Point for the center $\frac{1}{4}$ sec. cor. of sec. 3, at intersection with the E. and W. center line.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	C $\frac{1}{4}$ S 3 1964
	from which
	A fir, 9 ins. diam., bears S. 70 $\frac{3}{4}$ ° E., 20 lks. dist., mkd. C $\frac{1}{4}$ S3 BT.
	A fir, 13 ins. diam., bears N. 7 $\frac{3}{4}$ ° W., 56 lks. dist., mkd. C $\frac{1}{4}$ S3 BT.
	Ascend 450 ft. over SE. slope.
54.90	Dirt road, 25 lks. wide, bears N. 40° E. and S. 40° W.
73.89	The $\frac{1}{4}$ sec. cor. of sec. 3 only, on the N. bdy. of the Twp.
	From the $\frac{1}{4}$ sec. cor. of secs. 2 and 3.
	N. 86° 06' W., on the E. and W. center line of sec. 3.
	Ascend 125 ft. over SE slope, changing to S. slope, through scattering timber and light undergrowth.
13.20	Ravine, drains S. 55° E.; asc. 180 ft. over NE. slope.
20.30	Spur, slopes S. 10° E., and dirt road, 25 lks. wide, bears N. 10° W. and S. 10° E.; desc. 80 ft. over SW. slope.
24.30	Ravine, drains S. 10° W.; asc. 70 ft. over SE. slope.
27.00	Spur, slopes S. 15° W.; desc. 150 ft. over SW. slope.
33.15	Creek, 2 lks. wide, course S.; asc. 180 ft. over SE. slope.
39.03	The center $\frac{1}{4}$ sec. cor. of sec. 3.
	Ascend 125 ft. over SE. slope.
44.95	Spur, slopes S.; desc. 125 ft. over SW. slope.
51.10	Ravine, drains S. 35° W.; asc. 165 ft. over SE. slope.
56.95	Spur, slopes S.; desc. 20 ft. over SW. slope.
57.91	Point for the center W $\frac{1}{16}$ sec. cor. of sec. 3.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 23 ins. in the ground, with brass cap mkd.
	C $\frac{W \frac{1}{16}}{S 3}$ C 1964
	from which