

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of N. Bdy., T. 31 S. R. 6 W.

CHAINS

A maple, 20 ins. diam., bears N. 80° W., 11 lks. dist., has been remarked, illegible scribe marks visible on partly healed blaze.

and bearing trees marked by Irving

An oak, 11 ins. diam., bears N. 35° E., 122 lks. dist., with healed blaze.

A yew, 6 ins. diam., bears S. 19° E., 40 lks. dist., with illegible scribe marks visible on partly healed blaze.

A fir, 15 ins. diam., bears S. 71° W., 32 lks. dist., with scribe marks T31S R6W S5 CS visible on bark blaze, and with healed blaze at base.

Add marks BLM 1965 to brass cap.

N. 89° 10' W., bet. secs. 5 and 32, marking and blazing the true line.

Ascend 545 ft. over E. slope, across logged area, through scattering timber and dense undergrowth.

20.00 Enter open meadow, edge bears generally N. and S.

27.00 Spur, slopes N.; desc. 20 ft. over NW. slope.

35.00 Bottom of descent, slopes N.; asc. 5 ft. over E. slope.

38.00 Enter logged area with heavy young timber and dense undergrowth, edge bears generally N. and S.

39.85 The $\frac{1}{4}$ sec. cor. of secs. 5 and 32, perpetuated with an iron pipe, $\frac{3}{4}$ in. diam., firmly set, extending 18 ins. above ground, from which the remains of the original bearing trees

The rotted remains of a madrone stump, 16 ins. diam., bears N. 4° E., 71 lks. dist., with no marks remaining.

The stump hole of an oak, bears S. 24° W., 50 lks. dist., (Record, S. 21° W.)

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 30 S R 6 W
 $\frac{1}{4}$ S 32
 S 5
 T 31 S
 1965

from which new bearing trees

A fir, 6 ins. diam., bears N. $2\frac{1}{2}$ ° W., 19 lks. dist., mkd. $\frac{1}{4}$ S32 BT.

A madrone, 40 ins. diam., bears S. 52° W., 91 lks. dist., mkd. $\frac{1}{4}$ S5 BT.

Deposit iron pipe alongside the iron post.