

County Surveyor's Record, Douglas County, Oregon

, Dependent resurvey, Subdivisional Lines, T. 31 S., R. 3 W.

CHAINS

from which new bearing trees

A fir, 18 ins. diam., bears N. 17° W., 22 lks.
dist., mkd. $\frac{1}{4}$ S10 BT.

A fir, 17 ins. diam., bears S. 62° W., 9 $\frac{1}{2}$ lks.
dist., mkd. $\frac{1}{4}$ S15 BT.

Reset original corner stone alongside the iron post.

Corner is located at the head of a ravine, drains N. 85° E.

S. 89° 11' W., beginning new measurement.

Ascend 490 ft. over broken NE. slope.

17.00 Ridge, bears N. 20° W. and S. 30° E.; desc. 165 ft. over NW. slope.

26.00 Spur, slopes N. 70° W.; desc. 450 ft. over SW. slope.

39.90 The cor. of secs. 9, 10, 15 and 16, determined at record bearing and distance from the remaining original bearing trees:

A madrone clump, bears N. 12 $\frac{1}{2}$ ° E., 84 lks. dist.

A fir, 66 ins. diam., bears S. 43 $\frac{1}{2}$ ° E., 74 lks.
dist., with a healed blaze.

A down fir, 42 ins. diam., bears S. 50 $\frac{1}{2}$ ° W., 38 $\frac{1}{2}$ lks.
dist., with scribe marks T 3 S R visible on
opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

T	31	S	R	3	W
	S	9	S	10	
	S	16	S	15	
				1964	

from which new bearing trees

A fir, 7 ins. diam., bears N. 12° E., 15 $\frac{1}{2}$ lks.
dist., mkd. T31S R3W S10 BT.

A fir, 10 ins. diam., bears S. 9° W., 88 $\frac{1}{2}$ lks.
dist., mkd. T 31S R3W S16 BT.

A cedar, 34 ins. diam., bears N. 46° W., 97 lks.
dist., mkd. T31S R3W S9 BT.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, chinquapin, alder, madrone, cedar,
dogwood, live oak, maple, pine, and yew;

Undergrowth, vine maple, salal, Oregon grape, fern, hazel,
ocean spray, poison oak, huckleberry, blackberry, rhododendron,
and manzanita.