

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 31 S., R. 3 W.

CHAINS

Subdivision of Section 10,
T. 31 S., R. 3 W., Willamette Meridian,
Oregon

The following subdivision of section 10 was executed in conformity with legal surveying practice. The record of true line notes, only, is set forth in the following field notes.

From the $\frac{1}{4}$ sec. cor. of secs. 10 and 15.

N. $0^{\circ} 06' W.$, on the N. and S. center line of sec. 10.

Descend 120 ft. over broken NE. slope, through heavy timber and dense undergrowth.

- 7.73 Creek, 1 lk. wide, course E.; asc. 110 ft. over SE. slope.
- 15.30 Spur, slopes E.; desc. 280 ft. over NE. slope.
- 24.65 Creek, 1 lk. wide, course E.; asc. 145 ft. over broken SE. slope.
- 35.30 Spur, slopes N. $80^{\circ} E.$; desc. 60 ft. over NE. slope.
- 37.40 Ravine, drains E.; asc. 70 ft. over SE. slope.
- 39.88 Point for the center $\frac{1}{4}$ sec. cor. of sec. 10, at intersection with the E. and W. center line.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.
- T. 31 S R 3 W
C $\frac{1}{4}$ S 10
1964
- from which
- A pine, 11 ins. diam., bears S. $81^{\circ} E.$, 41 lks. dist., mkd. C $\frac{1}{4}$ S10 BT.
- A pine, 10 ins. diam., bears S. $13^{\circ} W.$, 30 lks. dist., mkd. C $\frac{1}{4}$ S10 BT.
- Ascend 55 ft. over SE. slope.
- 42.00 Spur, slopes E.; desc. 160 ft. over NE. slope.
- 47.95 Creek, 1 lk. wide, course S. $75^{\circ} E.$; asc. 330 ft. over SE. slope.
- 57.00 Spur, slopes SE.; desc. 190 ft. over Broken NE. slope.
- 70.47 Creek, 1 lk. wide, course E.; asc. 245 ft. over SE. slope.
- 79.60 Spur, slopes S. $70^{\circ} E.$; desc. 10 ft. over NE. slope.
- 80.36 The $\frac{1}{4}$ sec. cor. of secs. 3 and 10.