

County Surveyor's Record, Douglas County, Oregon

T. 23 S., R. 8 W.

CHAINS

The history of surveys of T. 23 S., R. 8 W., pertaining to the perpetuation of corner points as provided for in the General Special Instructions, Group 350 Oregon, dated May 3, 1957; "Investigation of Collateral or Physical Evidence of Corner Positions and accessories Followed by Remonumentation of Corner Points, With New Accessories When Needed", is as follows:

Subdivisions Williams R. Whipple 1894

The monumentation of corner points was requested by the District Manager of the Coos Bay Dist. Office for administrative purposes.

The corner of secs. 8, 9, 16 and 17, monumented with an iron pipe, 2 ins. diam., set 20 ins. in the ground, firmly set, from which the remains of the original bearing trees:

A fir, dead and fallen, 18 ins. diam., bears S. 40° E., 33 lks. dist., with an exposed and burned face.

A fir, dead and fallen, 30 ins. diam., bears S. 53½° W., 47 lks. dist., from which scribe marks are chopped out and exposed.

A stump, burned, bears N. 30° W., 14 lks. dist.

At the corner point

Set an iron post, 30 ins. long, 2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T23S R8W

S 8	S 9
S 17	S 16

1958

from which

A fir snag, 50 ins. diam., bears N. 12° E., 228 lks. dist., mkd. T23S R8W S9 BT.

A white fir, 7 ins. diam., bears S. 57½° E., 296 lks. dist., mkd. T23S R8W S16 BT.

A white fir, 12 ins. diam., bears S. 26° W., 173 lks. dist., mkd. T23S R8W S17 BT.

A fir stump, 34 ins. diam., bears N. 15° W., 42 lks. dist., mkd. T23S R8W S8 BT.

Reset the iron pipe alongside the iron post.

This corner falls on a bench, which has been clear cut and burned.

The ¼ sec. cor. of secs. 8 and 17, monumented with an iron pipe, 2 ins. diam., set 18 ins. in the ground, firmly set, from which the remains of the original bearing trees:

A fir stump, 50 ins. diam., bears S. 84° E. 32 lks. dist., no marks remaining. (Record bearing: S. 48° E.)

A stump hole, bears N. 59° W., 92 lks. dist.