

County Surveyor's Record, Douglas County, Oregon

T. 23 S., R. 8 W.

CHAINS

And two additional accessories:

A fir stump, 50 ins. diam., bears S. 17° W., mkd. RP $\frac{1}{4}$ SB/17.

A fir stump, 50 ins. diam., bears N. 23° W., with dim scribe marks on weathered face.

Each of these stumps is also marked with arusted and scorched metal General Land Office location poster and a General Land Office Warning to Tresspasser poster.

At the corner point

Set an iron post, 30 ins. long, 2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 23 S R 8 W

$\frac{1}{4}$ $\frac{S}{S}$ $\frac{8}{17}$

1958

from which

A hemlock, 6 ins. diam., bears N. 8° E., 88 lks. dist., mkd. $\frac{1}{4}$ S8 BT.

A hemlock, 20 ins. diam., bears S. 82½° W., 211 lks. dist., mkd. $\frac{1}{4}$ S17 BT.

Reset the iron pipe alongside the iron post.

This corner falls on a steep W. slope, on the edge of timber, bearing E. and W.

GENERAL DESCRIPTION

The land in the vicinity of these corners is steep and mountainous, with an elevation that ranges from 800 to 1100 ft. above sea level. An unused eroded logging road winds through sections 8 and 9, and in the immediate locale of the cor. of secs. 8, 9, 16 and 17. The soil is a rock, lumpy clay. The closest town is Elkton, approximately seven miles in a north-easterly direction.