

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of W. Bdy., T. 33 S., R. 6 W.

CHAINS

A Douglas fir, 20 ins. diam., bears N. 36° W.,
35 lks. dist., with a healed blaze.

A Douglas fir, 26 ins. diam., bears S. 67° E.,
87 lks. dist., with a healed blaze.

Set an iron post, 30 ins. long, 2½ ins. diam., 26 ins.
in the ground, with brass cap mkd.

R 7 W R 6 W
S 1 | S 6
T 33 S
SC
WC
1963

from which

A Douglas fir, 14 ins. diam., bears S. 78° E.,
90 lks. dist., mkd. XBT.

A live oak, 12 ins. diam., bears S. 29° W.,
128 lks. dist., mkd. XBT.

Reset the iron pipes inside the iron post.

descend 10 ft. over N. slope.

80.80 Left bank of Cow Creek, bears N. 80° E. and S. 80° W.,
course S. 80° W.

81.08 True point for the standard corner of Tps. 33 S.,
Rs. 6 and 7 W., determined from the only remaining
original bearing tree:

An ash, 14 ins. diam., bears S. 70° W., 35 lks.
dist., with a rotted face, no marks remaining.

The corner point falls in Cow Creek, 110 lks. wide,
5 ft. deep, course S. 80° W., curving N. 65° W., where
it is impracticable to establish a permanent monument.

Land, mountainous.

Soil, rocky clay.

Timber, Douglas fir, scattering ponderosa pine and
incense cedar; Undergrowth, manzanita, white thorn,
ceanothus, vine maple, devil's club and poison oak.

Dependent Resurvey of a Portion of the Subdivisional
Lines, T. 33 S., R. 6 W., Willamette Meridian, Oregon.

(Restoring the 1882 survey by William H. Byars)

From the cor. of secs. 7, 8, 17 and 18, remonumented
by the Douglas County Surveyor, in 1963, from the
original bearing trees, with an iron post, 1½ ins.
diam., firmly set, protruding 12 ins. above the
ground, with brass cap mkd.

DOUGLAS COUNTY
S 7 | S 8 T33 S
S 18 | S 17 R 6 W
1963
SURVEYORS OFFICE