

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 33 S., R. 6 W.

CHAINS

A madrone, 8 ins. diam., bears S. 10° E.,
12 lks. dist., mkd. S 8 T33S R6W 6S BT.

A madrone, 8 ins. diam., bears S. 20° W.,
11 lks. dist., mkd. S7 T33S R6W 6S BT.

There are no suitable bearing trees or objects
available in the NE. and NW. quadrants.

Land, mountainous.

Soil, rocky clay.

Timber, Douglas fir and scattering of incense cedar;
Undergrowth, vine maple, chinquapin, ceanothus, alder,
arrowwood, madrone, manzanita, and poison oak.

N. 89° 44' W., bet. secs. 6 and 7.

Ascend 155 ft. over NE. slope.

5.80 Spur, slopes S. 70° E.; asc. 205 ft. over SE. slope,
changing to E. slope.

12.20 Road, unimproved, bears N. 80° E. and S. 35° W.

19.37 Point for the E 1/16 sec. cor. of secs. 6 and 7.

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins.
in the ground, with brass cap mkd.

$$\begin{array}{r} \text{S } 6 \\ \text{E } 1/16 \text{ } \overline{\text{S } 7} \\ 1964 \end{array}$$

from which

A Douglas fir, 8 ins. diam., bears N. 14° W.,
32 lks. dist., mkd. E 1/16 S6 BT.

A Douglas fir, 12 ins. diam., bears S. 23° W.,
94 lks. dist., mkd. E 1/16 S7 BT.

Ascend 5 ft. over NE. slope.

19.70 Spur, slopes S. 60° E.; asc. 560 ft. over E. slope,
changing to SE. slope.

38.74 The ¼ sec. cor. of secs. 6 and 7, determined from the
remains of the original bearing trees:

A madrone stump, size indeterminate, bears
N. 72° E., 28 lks. dist., with no marks
remaining. (Record, 32 lks.)

A Douglas fir snag, 30 ins. diam., bears
S. 5° E., 10 lks. dist., mkd. ¼ S on opened
blaze.

At the corner point

Set an iron post, 30 ins. long, 2½ ins. diam., 26 ins.
in the ground, with brass cap mkd.

*FD OK
BY G. M. GREN
3/19/64 4118-19*

$$\begin{array}{r} \text{T } 33 \text{ S } \text{ R } 6 \text{ W} \\ \frac{1}{4} \text{ } \overline{\text{S } 6} \\ \text{S } 7 \\ 1964 \end{array}$$

from which