

County Surveyor's Record, Douglas County, Oregon

Remonumentation, Original Corner Points, T. 33 S., R. 6 W.

CHAINS

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
$$\begin{array}{r} T\ 33\ S\ R\ 6\ W \\ \frac{1}{4}\ S\ 35 \\ \hline S\ 2 \\ T\ 34\ S \\ 1963 \end{array}$$

from which

A Douglas fir, 9 ins. diam., bears N. 20° E., $74\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S35 BT.

Insert iron pipes inside iron post.

The $\frac{1}{4}$ sec. cor. of secs. 4 and 33, on the S. bdy. of the Township, monumented with an iron pipe, 1 in. diam., firmly set, protruding 18 ins. above the ground, from which the remains of the original bearing trees:

A shattered ash stump, 10 ins. diam., bears S. 15° E., 70 lks. dist., with partial, illegible scribe marks.A black oak stump, 20 ins. diam., bears N. 45° W., 28 lks. dist., with a rotted blaze and old axe marks.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
$$\begin{array}{r} T\ 33\ S\ R\ 6\ W \\ \frac{1}{4}\ S\ 33 \\ \hline S\ 4 \\ T\ 34\ S \\ 1963 \end{array}$$

from which

A Douglas fir, 10 ins. diam., bears N. $46\frac{1}{2}^{\circ}$ W., $47\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S33 BT.A Douglas fir, 16 ins. diam., bears S. 43° E., 107 lks. dist., mkd. $\frac{1}{4}$ S4 BT.

Insert iron pipe inside iron post.

The cor. of secs. 5, 6, 31 and 32, monumented with an iron axle, $2\frac{1}{2}$ ins. diam., firmly set in concrete of unknown depth, protruding 8 ins. above the concrete deposit, from which the remaining original bearing trees:

A black oak stump, size indeterminate, bears N. 5° E., 39 lks. dist., with axe marks.A black oak stump, size indeterminate, bears N. 52° W., 69 lks. dist., with axe marks.

At the corner point

Stamp the iron axle as it is impracticable to disturb the monument.