

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 7 W.

CHAINS

37.88

The cor. of secs. 9, 10, 15 and 16, determined at record bearing and distance from the original bearing trees:

An oak, 16 ins. diam., bears S. 76° E., 61 lks. dist., with scribe marks BT visible on partly open blaze.

The burned and rotted remains of a cedar, size indeterminate, bears S. 20° W., 62 lks. dist., no marks remaining.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 30 S		R 7 W	
S 9		S 10	
S 16		S 15	
1965			

from which new bearing trees

A pine, 20 ins. diam., bears N. 53½° E., 273 lks. dist., marked T30S R7W S10 BT.

A cedar, 27 ins. diam., bears S. 64° W., 305 lks. dist., marked T30S R7W S16 BT.

A cedar, 45 ins. diam., bears N. 10° W., 98 lks. dist., marked T30S R7W S9 BT.

From this point United States Coast and Geodetic Survey triangulation station, Buck Mountain, 1942, bears N. 2° 13' E., 19.53 chs. dist., monumented with a brass cap, 3½ ins. diam., firmly set in concrete.

Land, mountainous.

Soil, rocky clay loam

Timber, fir, white fir, cedar, madrone, pine, yew, chinquapin, live, oak, oak, and hemlock, undergrowth, vine maple, hazel, poison oak, Oregon grape, salal, manzanita, huckleberry, blackberry, fern, and ocean spray.

From the cor. of secs. 10, 11, 14 and 15.

S. 88° 11' W., bet. secs. 10 and 15.

Ascend 20 ft. over NE. slope, through heavy timber and dense undergrowth.

2.30 Apur, slopes N.; desc. 135 ft. over NW. slope.

11.60 Ravine, drains N.; asc. 25 ft. over NE. slope.

13.80 Spur, slopes N.; desc. 125 ft. over W. slope.

22.05 Creek, 1 lk. wide, course N.; asc. 185 ft. over NE. slope.

28.40 Spur, slopes N.; desc. 190 ft. over NW. slope.

34.45 Creek, 1 lk. wide, course N. 40° E.; asc. 280 ft. over E. slope.

41.06 Point for the ¼ sec. cor. of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.